

FULCRUM ID	Verification Component ID	latitude	longitude
9381725b-5b7b-4d5b-b7dc-5b296114e4f4	MLM-INFRA-2022000120	-23.0443	29.92375
5c98413f-fd96-47e3-81ab-f274848ff939	MLM-INFRA-2022000119	-23.0427	29.91997
68f04fd2-7296-4d9c-8d05-d3516261db61	MLM-INFRA-2022000109	-23.052	29.92412
1c4b2f82-9fb7-43a6-ac2c-e9bd2dacf134	MLM-INFRA-2022000103	-23.0535	29.92554
356279a8-259d-44af-979e-8c78c641158b	MLM-INFRA-2021003249	-23.1166	30.2125
5da25dd1-fbae-4e32-af91-f828b8d7e44c	MLM-INFRA-2021003237	-23.1158	30.21706
7eaa90f6-a2fe-4b69-b9e4-7d43306ca7c1	MLM-INFRA-2021003231	-23.1178	30.21808
d57a8d91-59af-48ee-a0fb-b0cca072b289	MLM-INFRA-2021003226	-23.1189	30.21794
2c85255b-d1c9-4320-b1f3-3b7b4fc1c938	MLM-INFRA-2021003201	-23.1158	30.21673
b5807783-858d-43f8-91b6-1a5b5bdebe7b	MLM-INFRA-2021003170	-22.8103	29.95182
60635365-1693-4ad6-abfe-f15614537201	MLM-INFRA-2021003158	-22.7987	29.95232
33a20442-9aef-4906-8d54-0d80bf906be3	MLM-INFRA-2021002979	-22.5089	30.22252
7f088a75-0b37-4fba-a65b-8d18d7a310e8	MLM-INFRA-2021002900	-22.7977	29.9529
2eef84b0-45d7-41fd-985b-a0ca508b158d	MLM-INFRA-2021002894	-22.7984	29.95245
7e5ee70a-cad8-4b7d-a2b3-e27856d88552	MLM-INFRA-2021002891	-22.7996	29.95219
0d9843bd-49f6-4448-adf3-e829d724e4fe	MLM-INFRA-2021002880	-22.8034	29.95216
5aaee498-3a24-4269-96a2-22504d831378	MLM-INFRA-2021002877	-22.8043	29.95214
b1504e8e-02c9-43ff-be65-84bddb2a3c84	MLM-INFRA-2021002876	-22.8051	29.95213
055d6675-b3c6-495a-aac6-3c48c7c91c6b	MLM-INFRA-2021002873	-22.8071	29.95197
c032bce1-325b-4f1c-ba19-928b21f478f8	MLM-INFRA-2021002872	-22.807	29.95197
eff7d0ff-d9bd-4c6e-9c0e-3d28e2720d92	MLM-INFRA-2021002870	-22.807	29.95207
c43a05de-4486-4435-a767-72ee83ed30aa	MLM-INFRA-2021002866	-22.8071	29.95207
0bbbfb8b-849f-498a-b1fb-4f8b985683b6	MLM-INFRA-2021002865	-22.8011	29.95218
a7887e6f-dfaa-4767-a407-e7a3e8d29fee	MLM-INFRA-2021002830	-22.894	30.1668
980a6ea7-157c-4cf1-a87b-4577702b9e93	MLM-INFRA-2021002738	-22.9032	30.03054
a8b1d023-8bf5-4301-a3f3-14d3d38bdfb7	MLM-INFRA-2021002693	-22.9753	30.10056
70aeb26b-1341-435d-8f52-6b2801c3d09d	MLM-INFRA-2021002263	-23.0554	29.90266
673e602e-7a89-4edd-b62c-83dd6c214b9a	MLM-INFRA-2021002259	-23.0556	30.2892
973c8334-d738-49ac-9ffb-f55aad32b158	MLM-INFRA-2021002258	-23.0556	30.28909
3dcb5a44-38f5-40b0-8954-51841a3703a4	MLM-INFRA-2021002252	-23.0559	29.90404
a67c937d-893f-4454-8257-b2691de22c15	MLM-INFRA-2021002251	-23.056	29.90429
e36f6267-f100-47bd-a052-a8987d6f6ddc	MLM-INFRA-2021002246	-23.0565	29.90563
ec88bb26-4779-4379-80e1-c42213d58887	MLM-INFRA-2021002245	-23.0566	29.90566
475b19eb-888d-4990-8b9c-5bba0a683176	MLM-INFRA-2021002139	-23.0831	30.32397
a55dac75-228d-4e05-b742-d56e77923ebf	MLM-INFRA-2021001876	-23.1508	30.07765
d96cefcb-832d-41d4-addc-e86291a5b0d9	MLM-INFRA-2021001867	-23.1538	30.07
d03ead77-c8d7-4c34-94fd-b0fe28600fec	MLM-INFRA-2021001821	-23.1616	30.07695
df03e017-208c-4fab-8c2a-5ac68860ec67	MLM-INFRA-2021001804	-23.1643	30.06226
03d5c42a-91a0-46b1-971b-5e259a9317b5	MLM-INFRA-2021001604	-23.2174	30.14527
190584de-057a-426a-87e8-13029276d33b	MLM-INFRA-2021001594	-23.2202	30.14443

d641749b-1782-4bcb-8d77-1391b5eb95b7	MLM-INFRA-2021001576	-23.2273	30.14029
a9134e96-b40a-4cdc-8f98-b6db9a0fa6cf	MLM-INFRA-2021001572	-23.229	30.13985
a3f34f75-8669-44ad-b787-7d2d217c35a4	MLM-INFRA-2021001553	-23.2339	30.13945
e48a3ba4-ca0d-4841-819e-8eb499818c56	MLM-INFRA-2021001467	-23.2463	30.14217
9305fdd7-29cd-4fca-acc4-4ad19cfb6f1f	MLM-INFRA-2021001364	-23.275	30.18062
f1e2bfec-a9bb-4344-ba16-60084ccbde41	MLM-INFRA-2021001254	-22.8991	30.03792
f1f4ca90-6ef7-4604-89f3-24b153112345	MLM-INFRA-2021001240	-22.9011	30.03468
ed8d7ee5-1d48-4f83-a5d5-9c7b4b55bf63	MLM-INFRA-2021001214	-22.9011	30.03253
025b42cb-23e2-469a-a923-381cd55d18a8	MLM-INFRA-2021001199	-22.9017	30.02897
99555c16-eef0-4daf-b19e-22615ada7386	MLM-INFRA-2021001195	-22.9014	30.02682
d1629c14-d186-4b29-9ec9-82e733e10d87	MLM-INFRA-2021001193	-22.903	30.02651
62bdcaec-e4d4-4119-9797-a0d30d694423	MLM-INFRA-2021001192	-22.9028	30.02646
0e4897f0-f30a-4d49-9db7-78b32f9fbe38	MLM-INFRA-2021001181	-23.0338	29.9286
dd3bbf6f-7a10-4161-b85c-eb35eed9129d	MLM-INFRA-2021001180	-23.0337	29.92855
8b47eb6a-f23a-434b-8138-bf630cebe076	MLM-INFRA-2021001175	-23.0368	29.92792
9f602330-3dd8-4bd0-a462-096e5c1f0765	MLM-INFRA-2021001174	-23.0368	29.92792
74731567-81ae-4cc5-ba54-fa7fed69a6d6	MLM-INFRA-2021001123	-23.037	29.92468
79df068f-a7a4-4efa-b417-841acde52e9b	MLM-INFRA-2021001067	-23.0368	29.92317
87e7c2c6-9926-4e97-ae31-42d24ffe0a5f	MLM-INFRA-2021001066	-23.0369	29.92312
9d00a08f-21e2-43bd-b4e5-86032a78872e	MLM-INFRA-2021001051	-23.0533	29.92235
00b38776-5d78-4d79-978a-d6647fabc719	MLM-INFRA-2021001049	-23.0367	29.92228
a0b2c539-896c-4207-ab47-39837f8a08f6	MLM-INFRA-2021000983	-23.0509	29.92042
b29b5ec8-ccf3-4596-bd4f-9fe7d93b32a0	MLM-INFRA-2021000868	-23.0513	29.91776
602475a1-d267-498f-8a6d-a143568d6922	MLM-INFRA-2021000791	-23.0397	29.91329
cdae5783-d733-4359-ac44-171357342bd0	MLM-INFRA-2021000777	-23.0445	29.91284
2ed4a034-0b32-481a-ab3a-2ac6e454c7c7	MLM-INFRA-2021000581	-23.0433	29.90866
b8f50a48-8c9e-4ba9-ae53-3bf7a7ab4514	MLM-INFRA-2021000124	-23.0464	29.87794
295e9106-eea7-4b78-bc23-da3e816907ea	MLM-INFRA-2021000002	-23.0706	29.64549
4f82c83d-c1b3-438f-bfc5-4bc0e2a51e00	MLM-INFRA-0000017437	-22.973	30.1231
94bfc72d-0025-4078-8b91-625094f0fe8e	MLM-INFRA-0000017023	-23.0669	29.62165
b0f7f8d2-2a56-4c7f-b4d7-9791b1f7460a	MLM-INFRA-0000017021	-23.0667	29.62173
3b261f0e-67ce-4abf-a958-a90933100e8a	MLM-INFRA-0000015909	-23.0963	30.39126
5b69e2d9-9a3c-422e-b154-520df0e6f5a9	MLM-INFRA-0000015904	-23.0969	30.39228
12dee459-df80-48a2-b1e8-374864651dbc	MLM-INFRA-0000015902	-23.0969	30.39237
b25e62c1-94f9-4602-ac70-9381b75e43ab	MLM-INFRA-0000015897	-23.0992	30.39598
28a97bc0-8cf0-4be1-90ef-56ad62f0d2fb	MLM-INFRA-0000015895	-23.0993	30.39603
5150bdc1-3876-431e-af3c-6299ab8e5fc3	MLM-INFRA-0000015894	-23.0952	30.38832
bcf8a15e-56fb-4f8b-9891-1f658feda12d	MLM-INFRA-0000015892	-23.0959	30.38677
eae79b2e-8b66-4a85-af4f-9d1796c64b3a	MLM-INFRA-0000015887	-23.0945	30.38652
7997df45-b949-40ea-a9b0-2c537d08ffa7	MLM-INFRA-0000015886	-23.0944	30.38664
2b163124-457f-4a24-954a-108eae42057c	MLM-INFRA-0000015885	-23.0943	30.38652
a6aaecba-0741-4343-9dd1-4e700a1781b3	MLM-INFRA-0000015883	-23.0938	30.38642
51443d4a-c4ea-4829-ada9-4239e39bbb01	MLM-INFRA-0000015879	-23.0929	30.38634
bb196fdd-c806-4897-8e99-ed25abb30a12	MLM-INFRA-0000015876	-23.092	30.38633
449f8c2f-6593-4990-99af-2e8a8f9ee023	MLM-INFRA-0000015874	-23.0914	30.38639
26b4c22d-e121-479e-ab59-83119b37523d	MLM-INFRA-0000015873	-23.0904	30.38653
ca256708-f32a-4e3d-8790-48c4dfaead1f	MLM-INFRA-0000015832	-23.0904	30.38642
aa8eb91d-851c-4c71-9154-6c2a70d33de2	MLM-INFRA-0000015813	-23.0468	29.87274

148eac49-b039-4ecc-bb33-65792f6fe2c9	MLM-INFRA-0000015797	-23.0481	29.88174
8e8ccb5-26ab-484e-b3ff-ed72f51e7b6f	MLM-INFRA-0000015795	-23.0497	29.88113
13c20b53-5772-4ff4-814f-33939f6b4fe7	MLM-INFRA-0000015787	-23.0504	29.88025
0a0ab4ae-da4e-4b1a-b3e0-12b58e8eab6e	MLM-INFRA-0000015786	-23.0502	29.87998
fc483064-83e9-4994-bc6b-dbbcd49bda17	MLM-INFRA-0000015781	-23.0468	29.88086
988a8502-e006-476f-b59f-8ddff1e8b695	MLM-INFRA-0000015775	-23.0462	29.88392
a093d498-6364-484a-bb21-21e3e7c423ac	MLM-INFRA-0000015752	-23.0457	29.881
c0208438-b6a0-4bb6-b68d-847bb36b86b8	MLM-INFRA-0000015751	-23.0453	29.87814
a49fddb3-7e2a-4ecd-94e7-78e4e5a2b2ab	MLM-INFRA-0000015741	-23.0487	29.87434
c72550fc-441c-4040-b8d4-93d26df17beb	MLM-INFRA-0000015718	-23.0726	29.89816
01071579-6ddb-4a9b-ad0e-be9bb7e644b6	MLM-INFRA-0000015714	-23.0512	29.92461
98c05e54-7fad-4948-b74c-9397f4dc9cd0	MLM-INFRA-0000015706	-23.0535	29.92166
85f27741-7d8c-46c7-9fbe-145cb49542db	MLM-INFRA-0000015687	-23.048	29.8963
105e242e-b174-48ff-b3bb-12bb5efe5cbd	MLM-INFRA-0000015667	-23.0341	29.92464
f3054c49-dc7c-4c04-9bef-88ad56dc238d	MLM-INFRA-0000015666	-23.0443	29.91982
b8247ac7-54ab-4a70-ad82-549146ab20d0	MLM-INFRA-0000015659	-23.0381	29.91209
81cb39da-d92b-4db8-8127-43a6c0f21e70	MLM-INFRA-0000015640	-23.0577	29.92869
80fd8d25-d3ee-43d4-b5b5-94fa444f9cf9	MLM-INFRA-0000015633	-23.0465	29.92257
c58b3449-ff11-4636-bc3c-7fe1b664455e	MLM-INFRA-0000015604	-23.0506	29.91919
eb315b18-b9cd-4b70-8bcf-dbd0812ac8da	MLM-INFRA-0000015571	-23.0297	29.92994
6628b641-2e45-412d-9751-7ad3c1ac95cd	MLM-INFRA-0000015543	-23.0443	29.92161
fd33b50e-1a76-4852-b98d-43f4f42d7146	MLM-INFRA-0000015523	-23.0255	29.92179
c884bb3f-7d33-41c6-853c-51b695ef1a38	MLM-INFRA-0000015473	-23.0329	29.90852
9ca734fe-4696-4630-a92a-946ecfff761b	MLM-INFRA-0000015465	-23.0426	29.91792
bab3c2f2-296c-4baa-91cb-dff103e66040	MLM-INFRA-0000015464	-23.037	29.92456
8fc22dea-fb79-4d6c-a618-7b9078b07c7b	MLM-INFRA-0000015426	-23.0487	29.90439
718e5ca4-1e91-495d-a43a-d68cb4926745	MLM-INFRA-0000015404	-23.0553	29.90265
0fdd9ec8-10ba-4750-afea-9040f493a44e	MLM-INFRA-0000015352	-23.0241	29.91013
4618544e-4871-4c57-82a1-c46a998456d7	MLM-INFRA-0000015331	-23.0269	29.9107
97a9c548-81bd-4249-9423-917d06d69b3d	MLM-INFRA-0000015288	-23.0348	29.91334
a8358b85-abf3-4d0c-9b9d-8d358efcf9a4	MLM-INFRA-0000015284	-23.0274	29.92762
65bd2559-0807-41b2-a93c-3b35120bb284	MLM-INFRA-0000015242	-23.0399	29.90939
697f9865-b0f9-4309-9e0d-3bc8874178f7	MLM-INFRA-0000015240	-23.0401	29.90934
c0b8b8fc-c22f-436f-9407-d3d077d5c27a	MLM-INFRA-0000015235	-23.0536	29.92924
ba4b8a12-f6d7-4dd8-a3db-56fcd3cd23c	MLM-INFRA-0000015223	-23.0492	29.92027
d2ccd6c9-a442-4b1f-a9de-52ef50d510f6	MLM-INFRA-0000015216	-23.0487	29.9195
0b595edc-22ec-407f-b72b-0738d5784dbc	MLM-INFRA-0000015188	-23.196	30.15276
87426685-470e-47e9-a372-f9569bc06b6c	MLM-INFRA-0000015169	-23.1942	30.15916
a8530edd-dd15-44e3-bd80-c11a6206c89a	MLM-INFRA-0000015011	-23.0646	30.3601
c33c307b-147c-4310-9900-c16561a8d5a0	MLM-INFRA-0000014998	-23.1585	30.07015
c2363753-70bf-405d-af8c-77f08357de8c	MLM-INFRA-0000014897	-23.0435	29.90884
b8dfdb1e-d094-4f26-bae4-3b4322989e4e	MLM-INFRA-0000014672	-23.0482	29.92258
2f700241-9325-4336-ad08-bbf4cab9e092	MLM-INFRA-0000014619	-23.0586	29.90113
30d3665b-a725-4530-9b9b-c039a759a12f	MLM-INFRA-0000014607	-23.0428	29.90827
f7f32a59-4ee6-4cd4-b101-51d117248b2f	MLM-INFRA-0000014536	-23.0982	29.73162

64576454-c5ef-40a5-97c8-01db7179d84a	MLM-INFRA-0000014535	-23.0468	29.90425
f6d344c5-7fb2-4bcb-b95a-dd46fb0aa191	MLM-INFRA-0000014507	-23.064	30.36049
826e5d08-bfa7-4c14-8b7d-284bc6b7ae4c	MLM-INFRA-0000014503	-23.2169	29.99569
84a726f9-9f0b-4f6e-a6ef-cf866f1bf570	MLM-INFRA-0000014502	-23.0536	29.92087
2eac5ca6-5b6b-48a1-a6ab-f8d1f7f69089	MLM-INFRA-0000014492	-23.1633	30.07016
d15389d3-b19c-497b-ab7c-42774f096f65	MLM-INFRA-0000014483	-22.8825	30.07553
938e4c0e-a337-4ca8-94dc-e719f62518de	MLM-INFRA-0000014465	-22.901	30.03306
52f1ceb3-dd32-4917-9c71-1b70a8adc2c2	MLM-INFRA-0000014449	-23.2166	29.99517
6231b4cb-77a8-4169-a7cd-0dea9804223c	MLM-INFRA-0000013917	-23.0517	29.90468
d35265c9-b42c-4afd-b776-367851deed8a	MLM-INFRA-0000013916	-23.0517	29.90473
efaf0ff6-10cb-4edd-bb65-bbc0b340e4cb	MLM-INFRA-0000013879	-23.1514	30.07261
8b71c205-4400-455e-ac5e-9cfda001561b	MLM-INFRA-0000013866	-23.2103	29.98863
20ef2ccc-2bf9-4ddd-9773-dac8e1c387ee	MLM-INFRA-0000013823	-23.0466	29.92206
a043d7d4-09e2-4ea2-ad7d-94632343c045	MLM-INFRA-0000013794	-23.0557	29.92588
8013c795-3cc4-489b-9b0b-45d61731198f	MLM-INFRA-0000013792	-23.0501	29.8691
884a9806-11cd-4665-8f20-52ed4cb6d3bf	MLM-INFRA-0000013787	-23.2102	29.9888
1989985c-0b58-4bfc-98b2-149782bd9e01	MLM-INFRA-0000013781	-23.1521	30.07181
9ef336cf-1d82-40c3-ba97-7867587df69e	MLM-INFRA-0000013780	-23.0482	29.87228
0191ac43-9f28-4fdd-be20-ab561533a4f7	MLM-INFRA-0000013766	-23.0466	29.92212
6884dff-b8ca-4916-a6bb-f002ada3d40d	MLM-INFRA-0000013737	-23.0466	29.92206
39f440a1-e9ad-48aa-bb72-1e14678cbf65	MLM-INFRA-0000013732	-23.1514	30.07255
2df9173b-ab11-4a2c-8693-29f4617f38af	MLM-INFRA-0000013639	-23.22	29.99003
be412a24-b463-438a-87ba-54b0a1827dc9	MLM-INFRA-0000013634	-23.2194	29.99078
0fe7124c-75e5-4161-9ea1-430c6b08dfce	MLM-INFRA-0000013630	-23.2194	29.99078
9eebef1d-7e32-41c6-8973-c09248997afe	MLM-INFRA-0000013629	-23.2194	29.99078
460023b3-e633-4ae8-96d2-ae97447f3f42	MLM-INFRA-0000013627	-23.2194	29.99079
5f95c540-4bb4-4569-b155-b647e1d9f6c6	MLM-INFRA-0000013626	-23.2194	29.99079
89a23928-2fa5-4f20-a9f0-c32ef33b9962	MLM-INFRA-0000013625	-23.2194	29.99079
ba25ca30-fce3-48b3-bf82-584bb9589e59	MLM-INFRA-0000013624	-23.2194	29.99079
5089dff-9f35-48e7-b02f-82b2c665868b	MLM-INFRA-0000013623	-23.2194	29.99161
c28c60e5-bc98-45a6-b43b-bb13153c59c3	MLM-INFRA-0000013622	-23.2193	29.99067
a99f0733-9303-4711-8937-d1a02065ab67	MLM-INFRA-0000013621	-23.2195	29.99077
a23c5c21-a57a-4204-a50c-c118fe0f7640	MLM-INFRA-0000013620	-23.2188	29.9904
19e28a00-ad8d-436e-bae3-7386ca60e047	MLM-INFRA-0000013615	-23.2188	29.99039
64234ef2-d432-4b21-933e-1a9993746437	MLM-INFRA-0000013611	-23.2188	29.9904
9170897a-fd38-4f36-85a5-18adf75b7d9c	MLM-INFRA-0000013610	-23.2188	29.9904
ad41471e-76da-45e1-8d4d-3c191795d021	MLM-INFRA-0000013609	-23.2188	29.9904
1cab6074-59de-4fbc-9bb9-334e6fb9e306	MLM-INFRA-0000013608	-23.2188	29.99039
d3994bca-4bd0-4dfe-b6a8-7ef26b41e318	MLM-INFRA-0000013607	-23.2188	29.99039
7b3aa18b-5f2a-4c12-a215-d24506740fe5	MLM-INFRA-0000013601	-23.2185	29.99007
10496fca-08e2-49b8-b60b-66491c8a0466	MLM-INFRA-0000013594	-23.2182	29.98999
a4ba0475-5ccd-4fbb-b768-7f591d600566	MLM-INFRA-0000013593	-23.2182	29.98999
9032aedf-e3b2-42b2-892d-1303868243f4	MLM-INFRA-0000013592	-23.2182	29.98999
3b04eebf-5c35-485c-bca7-70a86696330f	MLM-INFRA-0000013591	-23.2182	29.99

5f5bc656-62b6-4085-b206-3925382e3838	MLM-INFRA-0000013590	-23.2182	29.99
a75835f5-8f52-4f93-b7b7-eba082eabaa7	MLM-INFRA-0000013589	-23.2182	29.99
48a6d65f-0332-4e46-a8ed-d539ce9b5e4e	MLM-INFRA-0000013588	-23.2182	29.99
8a7ddb32-709a-4c64-a5f0-c8119afc5714	MLM-INFRA-0000013585	-23.2177	29.98964
3746b174-0cd9-460b-b488-3b5ce3e8d817	MLM-INFRA-0000013584	-23.2177	29.98964
65644479-c007-4359-974d-02e68ce01163	MLM-INFRA-0000013583	-23.2177	29.98965
ee877328-1bc7-44cf-82f9-55ce9a25f148	MLM-INFRA-0000013582	-23.2177	29.98964
20cccedb-809a-46c3-bbca-76eefed7b2a9	MLM-INFRA-0000013581	-23.2177	29.98964
5a4b9d18-8c71-4596-9782-b79462042a20	MLM-INFRA-0000013580	-23.2177	29.98965
f51d09cd-0bcf-42c8-b80c-08db27d868e9	MLM-INFRA-0000013579	-23.2177	29.98965
2605fc14-9224-46e5-998d-29a7176207c1	MLM-INFRA-0000013573	-23.2169	29.98934
ed7f0486-db12-4076-b5a4-f5a182e38fff	MLM-INFRA-0000013571	-23.2168	29.98935
903b77f1-cfa0-45e4-ace0-e9fe837e16ea	MLM-INFRA-0000013570	-23.2168	29.98935
68c065cb-1eca-4fab-abf5-082e8fd1a1a8	MLM-INFRA-0000013569	-23.2169	29.98934
6dec5ec6-b7f2-4827-a87d-793ec3c538bf	MLM-INFRA-0000013568	-23.2169	29.98934
2af2c71c-b905-4159-bdc6-422eba3c76ef	MLM-INFRA-0000013567	-23.2168	29.98935
4ba820ec-d0c0-44b6-9cbf-69a053cc860f	MLM-INFRA-0000013566	-23.2168	29.98935
44865881-0a31-405d-9483-a692d5a10d35	MLM-INFRA-0000013564	-23.2167	29.98936
6288ee00-9340-47f3-bb2e-89baf5bd32e6	MLM-INFRA-0000013563	-23.2167	29.98936
5393b405-8b1b-43b4-8b58-a98577b30183	MLM-INFRA-0000013562	-23.2167	29.98936
9b84ba79-b1fd-44a6-a45a-e1aca6cc496f	MLM-INFRA-0000013551	-23.2153	29.98943
3cd17528-c07a-4231-b130-ffe73fe8a905	MLM-INFRA-0000013549	-23.2153	29.98943
14ca1bb3-873a-48c8-b2c1-1e1170220fae	MLM-INFRA-0000013548	-23.2153	29.98943
f9e1613b-c17d-423e-a12a-ffdfdaab77bb	MLM-INFRA-0000013547	-23.2153	29.98943
86809d3b-609c-4fd3-86ba-fd81e4775e86	MLM-INFRA-0000013546	-23.2153	29.98943
e080b45a-cd2e-4bea-80ce-a436e19f1bb3	MLM-INFRA-0000013543	-23.2153	29.98943
25ab5d02-4802-480f-aa1e-f4e3b041d49d	MLM-INFRA-0000013542	-23.2153	29.98943
164517ae-9ab3-499b-8384-6880472d6f3a	MLM-INFRA-0000013534	-23.214	29.98944
b159f049-7553-4e0b-bf8f-95717d64abe2	MLM-INFRA-0000013533	-23.2092	29.98886
e684e525-1a48-4d3e-bb54-7c27ac5a67ce	MLM-INFRA-0000013530	-23.2134	29.98942
e206f4e2-037a-4e88-9376-b55d9e2098ea	MLM-INFRA-0000013526	-23.2127	29.98922
7a4f6734-d916-418b-a7ef-c0fd5770679b	MLM-INFRA-0000013524	-23.2134	29.98942
60eafc58-77eb-4385-b331-a1f347bfd8ca	MLM-INFRA-0000013523	-23.2134	29.98942
97006a4a-d632-40ab-8768-19a7968cad78	MLM-INFRA-0000013516	-23.2127	29.98922
f27b3664-c7af-47d6-9073-68d6d75379a2	MLM-INFRA-0000013515	-23.2127	29.98922
6563b9a0-7382-477d-8ee0-3a35ead24322	MLM-INFRA-0000013514	-23.2127	29.98924
99b4dfffc-62d0-4bd5-9c28-d9e2eefd2982	MLM-INFRA-0000013513	-23.2127	29.98924
93babaf3-9c9e-485f-a386-d2ea89d9c4af	MLM-INFRA-0000013512	-23.2127	29.98924
c670a3f3-e22f-4582-b7f8-e372b283e9fd	MLM-INFRA-0000013511	-23.2127	29.98924
10994742-4a38-4509-8732-04ea39b1507d	MLM-INFRA-0000013497	-23.2119	29.98897

c09dd69a-3ba5-4a5c-bc82-22083f9386c0	MLM-INFRA-0000013495	-23.2116	29.98864
6c8b235f-32c2-48b7-b6cf-d5a87977fa45	MLM-INFRA-0000013490	-23.2109	29.98876
32c1348d-1d4d-47e9-b01b-126bda599f92	MLM-INFRA-0000013488	-23.2109	29.98876
9bd3bec2-77ab-45e2-92eb-c81d30d1acf0	MLM-INFRA-0000013486	-23.2109	29.98876
ba568d82-d244-45c2-bef5-7c00adefb632	MLM-INFRA-0000013484	-23.2109	29.98878
15613991-3456-4e8a-9e05-e7ef2e436ee2	MLM-INFRA-0000013483	-23.2109	29.98878
138fe121-9b8d-43ab-803f-52f178a4539c	MLM-INFRA-0000013482	-23.2109	29.98878
7d333c15-ba05-458a-8071-f2f23f2997c6	MLM-INFRA-0000013481	-23.2109	29.98878
0bb67c8e-056e-472f-a033-e4126ad02771	MLM-INFRA-0000013474	-23.21	29.98863
75b01008-aea7-4dc5-9356-77c996c3c655	MLM-INFRA-0000013472	-23.2103	29.98816
d880cdb5-05ed-40bd-8b9c-541fa78d3b7d	MLM-INFRA-0000013470	-23.2104	29.98868
b0bec1ba-4fee-4516-b342-6f73edc9f4c3	MLM-INFRA-0000013468	-23.21	29.98861
eccf264c-396c-40df-947e-0ced182a2184	MLM-INFRA-0000013467	-23.21	29.98861
05393e8a-c28f-4802-af22-51d99b983b94	MLM-INFRA-0000013466	-23.21	29.98863
2ced37bb-8077-4ae0-8887-34984a9ad36a	MLM-INFRA-0000013465	-23.21	29.98863
d879701b-f456-4a63-98eb-9647ecf40cad	MLM-INFRA-0000013464	-23.21	29.98863
342572cb-6724-4dfb-9969-28c017b7f902	MLM-INFRA-0000013463	-23.21	29.98861
484b1624-63aa-4e7f-9a0a-7ab93ea9aaaf	MLM-INFRA-0000013457	-23.2092	29.98884
ebcaedec-c429-4f4b-ab73-40059a8960cc	MLM-INFRA-0000013454	-23.2092	29.98888
92a78bef-74eb-4527-8685-0db83799de10	MLM-INFRA-0000013450	-23.2092	29.98884
4850dc8e-824a-408c-80ee-4e3e8a69af3a	MLM-INFRA-0000013448	-23.2094	29.98871
e3c97aae-0aba-4633-88b1-730bdfb37b73	MLM-INFRA-0000013447	-23.2092	29.98884
3fa6b366-6d38-4c06-90d5-bfe8263cc3b2	MLM-INFRA-0000013446	-23.2092	29.98882
2f6fc928-545c-4290-adbe-14fbd2ebf18f	MLM-INFRA-0000013445	-23.2092	29.98882
3484de9b-4eb7-4afe-99ac-ff65a1b52af3	MLM-INFRA-0000013443	-23.2092	29.98884
611ba708-aca1-4e9d-8f03-a7d6558af9dc	MLM-INFRA-0000013442	-23.2092	29.98882
cab8d2a1-ef50-4c51-b340-6828b388a394	MLM-INFRA-0000013437	-23.2086	29.98905
fbf7ecb5-166f-4951-af3d-4127b79eab6f	MLM-INFRA-0000013436	-23.2086	29.98905
a587228f-7883-46cb-bc28-1472ab79363f	MLM-INFRA-0000013434	-23.2086	29.98907
2da0d05d-8af1-4017-8f3b-6d21615fea59	MLM-INFRA-0000013433	-23.2086	29.98907
6baaf8a6-8887-45a6-9d70-3ab5aca13d67	MLM-INFRA-0000013432	-23.2086	29.98907
a9b42029-349b-4f35-b8c7-627348c02eba	MLM-INFRA-0000013431	-23.2086	29.98907
3a5bd2d0-ef2d-4564-9ee6-a0813d0d2dc5	MLM-INFRA-0000013430	-23.2086	29.98905
e30b5695-b559-40b3-aba0-17965becb75e	MLM-INFRA-0000013421	-23.2079	29.98928
ba7254b4-216c-47da-868c-99ef084e8c75	MLM-INFRA-0000013419	-23.2079	29.98929
21fe7cad-8522-466a-8410-20f58ae9e2db	MLM-INFRA-0000013418	-23.2079	29.98929
f978ac0f-7da1-43be-bea7-75d77c46ca48	MLM-INFRA-0000013417	-23.2079	29.98929
97cdee59-9da8-42a8-a120-37e79d6e3ea6	MLM-INFRA-0000013416	-23.2079	29.98929
2285db22-e0b9-4dfb-bd35-d6da6cc86ed1	MLM-INFRA-0000013415	-23.2079	29.98928
936e7fc8-ea92-4611-9a47-71fa1854420f	MLM-INFRA-0000013414	-23.2079	29.98928

1b3c8e56-51fa-417e-a982-213012801bf0	MLM-INFRA-0000013406	-23.2069	29.98962
30ca4065-a77c-4b75-8236-2624c6d66384	MLM-INFRA-0000013402	-23.207	29.9896
ac3729ac-953f-43c9-96cd-8bb766f397f4	MLM-INFRA-0000013398	-23.207	29.9896
e96fe480-a7f5-430e-9ca3-801d6aeb3670	MLM-INFRA-0000013397	-23.207	29.9896
cff5f92b-cb46-48bb-a8a8-327d21cfb9b1	MLM-INFRA-0000013396	-23.2069	29.98962
251c7651-77e6-4aa2-a881-88bf8cc19c76	MLM-INFRA-0000013395	-23.2069	29.98962
d2e3cc3d-813b-4b6b-aadd-e791a35aa3d6	MLM-INFRA-0000013392	-23.207	29.9896
7acd4da5-097f-44c5-96a1-a626a9f34d61	MLM-INFRA-0000013388	-23.2063	29.98971
9462da48-fb58-442e-a333-db3e1e99d36d	MLM-INFRA-0000013263	-23.1561	30.07185
155e36dd-0bf6-4b88-864e-add2179e9121	MLM-INFRA-0000013184	-23.1618	30.0781
9f8e00d8-c462-4625-9e80-fccf34648c07	MLM-INFRA-0000013180	-23.1618	30.0781
9d1d80ce-9745-46ed-8da0-9f7354637326	MLM-INFRA-0000013176	-23.1617	30.07701
6e13b7b5-b649-4743-afe4-2b51229e5ece	MLM-INFRA-0000012977	-23.1577	30.07884
752ccc9d-0941-4d7b-b2c8-c4b59fe5b8b7	MLM-INFRA-0000012940	-23.1571	30.07572
960dda36-1dc5-45a4-9a69-639f493ebe86	MLM-INFRA-0000012833	-23.1557	30.07613
a246a870-c61e-445b-a77f-234ecb0ae0d4	MLM-INFRA-0000012789	-23.1565	30.07195
ad0671de-d253-4276-90b3-001c2611a292	MLM-INFRA-0000012755	-23.1541	30.06988
5fa556ad-3694-4a06-b4fd-a60b443dadfd	MLM-INFRA-0000012754	-23.1539	30.06993
c4702170-6200-4918-96d8-3e2f2ee70768	MLM-INFRA-0000012753	-23.154	30.06993
fe010846-9a62-44e6-868a-0bc63f9a362d	MLM-INFRA-0000012747	-23.1536	30.07037
aeb7e04d-12c0-440b-8dd9-c2c731904326	MLM-INFRA-0000012746	-23.1537	30.07037
e9b4eeec-77d8-474f-9b86-0d8775b8e4d5	MLM-INFRA-0000012745	-23.1537	30.07037
975d6f6a-b3f4-44d7-96e2-8bb376995124	MLM-INFRA-0000012733	-23.1534	30.07083
51dd266c-1512-4bbf-a45f-905db65b129e	MLM-INFRA-0000012732	-23.1534	30.07089
e39ac540-ba11-4f06-880a-5b0eb3018cc6	MLM-INFRA-0000012725	-23.1534	30.07085
7f98a71f-38fe-4a06-8ed8-094b85a8a7ad	MLM-INFRA-0000012712	-23.1526	30.07133
086419a9-b7fa-4f46-a397-a06aa080a0c9	MLM-INFRA-0000012711	-23.1526	30.07129
b6eb949a-0fda-43da-a6b8-2967c8dd5df5	MLM-INFRA-0000012709	-23.1526	30.07135
93b97b95-a98c-43e2-9e58-10771a5d7f42	MLM-INFRA-0000012704	-23.1514	30.07268
0ea079e4-35cd-4494-81b4-f8ca394661fd	MLM-INFRA-0000012703	-23.1522	30.07172
2f9db80a-a30d-4f69-8910-d3c280570cab	MLM-INFRA-0000012701	-23.1522	30.0717
43876a08-9dc4-498b-86c2-7f7295a6778d	MLM-INFRA-0000012696	-23.152	30.07761
4c04af5e-8d06-4569-ae9f-9264b476d1eb	MLM-INFRA-0000012695	-23.1522	30.07173
0ed7b1e9-50a6-447a-9505-b99ac75b6a8d	MLM-INFRA-0000012694	-23.152	30.07192
3a8c22ed-bea0-4ce6-be3e-18315173f427	MLM-INFRA-0000012693	-23.1514	30.07267
901609da-0661-42f5-8825-cd6e4087d4b1	MLM-INFRA-0000012690	-23.1516	30.07224
67b24e2c-70a4-4a9d-89e5-360faf090d8b	MLM-INFRA-0000012689	-23.1516	30.07224
5f9b1ada-1053-42ff-9b0d-0bc7ca409bd0	MLM-INFRA-0000012682	-23.1514	30.07268
7a990f92-3382-4ae6-8c87-8412032f7178	MLM-INFRA-0000012674	-23.1508	30.07652
2928e332-3523-4865-9b99-8919859028ab	MLM-INFRA-0000012672	-23.1513	30.073
bcbf0291-b579-4124-9dbf-d44eff0b750f	MLM-INFRA-0000012670	-23.1511	30.07323
2d693472-05b1-4e87-b109-4c0ef71c6b71	MLM-INFRA-0000012669	-23.151	30.07323
eb2e09d2-8728-4c6d-9417-89405216d939	MLM-INFRA-0000012668	-23.151	30.07323
87e663fd-8c96-412f-a7d1-632f255bd21b	MLM-INFRA-0000012664	-23.1508	30.07755
bc0777e4-9502-4e39-a33a-f9e512011a11	MLM-INFRA-0000012663	-23.1508	30.07755
5859e402-ff7a-4a92-891e-c1b67c2f7c22	MLM-INFRA-0000012662	-23.1508	30.07586
6fd4ce05-fd53-4d55-bc13-c5aab3fea48e	MLM-INFRA-0000012660	-23.1508	30.07707
68676fc5-f96d-49d0-8f89-0f289acfbfb8	MLM-INFRA-0000012659	-23.1508	30.07465

e97ee6f4-7b83-442e-9ee8-e7f66334d03f	MLM-INFRA-0000012657	-23.1508	30.0753
02dbb96e-ab4b-4683-a7ad-76f1b8c8fef3	MLM-INFRA-0000012656	-23.1508	30.07707
c0163565-6fff-4b0c-bf5e-14ccac239636	MLM-INFRA-0000012655	-23.1508	30.07399
d0d9b046-3c46-4372-9993-be169430119a	MLM-INFRA-0000012654	-23.1508	30.07399
ae758087-5923-4bfe-b337-48bea3443c1a	MLM-INFRA-0000012653	-23.1508	30.07399
597730f7-1db0-4380-9e2e-33da4e2471ce	MLM-INFRA-0000012652	-23.1508	30.07465
01b3f109-2399-4ed5-9102-f2272b6343db	MLM-INFRA-0000012651	-23.1508	30.07465
2113d3e0-4a42-4f55-9c37-50ab92ec4f1c	MLM-INFRA-0000012650	-23.1508	30.07586
8bb739db-780e-44f1-8a2f-a48f03e7cf02	MLM-INFRA-0000012649	-23.1508	30.07586
ba20635c-95b7-48ce-848a-c3d6729364c5	MLM-INFRA-0000012648	-23.1508	30.07754
81b9cf55-aa14-4359-969b-e8d6ad6abef4	MLM-INFRA-0000012647	-23.1508	30.0753
e58d03e7-80a1-45ed-adf8-eca6958f86af	MLM-INFRA-0000012646	-23.1508	30.0753
97a9b2aa-b387-492f-8a0f-ae075cda012d	MLM-INFRA-0000012645	-23.1508	30.07651
4328907f-1f39-43e1-a55c-9bef484fed8d	MLM-INFRA-0000012644	-23.1508	30.07707
712828c4-d493-42d2-ac15-2303bdbfaf8d	MLM-INFRA-0000012643	-23.1508	30.07651
f53ee11e-74b0-4e0d-bda3-ef35db7bd11d	MLM-INFRA-0000012632	-23.1506	30.07613
8351ea39-7b73-4aba-aacb-1da27e651afa	MLM-INFRA-0000012622	-23.1502	29.48643
79df9ee8-ca2f-41c3-9524-f2eb35fc9c4f	MLM-INFRA-0000012340	-23.1356	30.18023
e1b7de87-b479-4a7d-b774-c50b1a97dd03	MLM-INFRA-0000012337	-23.1355	30.0816
bf5bb922-5fe5-4061-9cf2-52995412542f	MLM-INFRA-0000012068	-23.1258	30.30158
751070d3-976a-49c6-b81e-346a7b877788	MLM-INFRA-0000012051	-23.1238	30.25526
574d151f-5cf4-4e04-8890-bb78f452bbff	MLM-INFRA-0000012030	-23.1199	30.23949
e9b2ee5d-3d41-45f4-ba05-746072b350b8	MLM-INFRA-0000011941	-23.1129	29.82227
27184541-9808-4c7a-82c9-31795cde2669	MLM-INFRA-0000011937	-23.1127	30.26166
f02e1fc3-f79c-4ffa-a073-ea88a67d3169	MLM-INFRA-0000011835	-23.1086	30.24033
682fcdeb-a486-4217-99a4-845efdae418e	MLM-INFRA-0000011822	-23.1079	30.24424
925d2c51-0ec3-4e28-85f7-0f4ec1670831	MLM-INFRA-0000011743	-23.105	30.22912
598482fd-fbbf-4801-af00-a8cda6cfb613	MLM-INFRA-0000011712	-23.1031	30.25098
f5dc99c3-6d5d-444d-abb0-ac6c0117999f	MLM-INFRA-0000011657	-23.1006	30.24023
2c9633bc-4323-4ab7-986f-397f6deaba68	MLM-INFRA-0000011641	-23.0999	29.92337
a14d6517-28d7-4747-b9fa-10caaaa0ca7c	MLM-INFRA-0000011584	-23.0984	30.25948
a328d386-1e2b-4721-a2ab-3504a1324b94	MLM-INFRA-0000011570	-23.0981	30.35683
9938ac95-44a3-4ba8-86f1-5aead6879b49	MLM-INFRA-0000011482	-23.0955	29.7842
2d5b7838-0820-43f3-a760-3f7b42f0e127	MLM-INFRA-0000011471	-23.095	30.35715
aa41726d-c31e-4277-9680-abb130b063ae	MLM-INFRA-0000011465	-23.0949	30.28654
5e7f70d5-70fb-4eb6-945a-27134401938c	MLM-INFRA-0000011403	-23.0931	29.68367
4979e613-591d-4d33-b112-7c8880895911	MLM-INFRA-0000011272	-23.09	29.93457
c876ef25-1356-4d8a-9977-cf249d078893	MLM-INFRA-0000011173	-23.0877	29.53737
22713136-607f-41c4-a893-04350d931b6e	MLM-INFRA-0000011013	-23.0847	30.30294
cc33fa07-348d-4823-b64a-c61d760167c4	MLM-INFRA-0000010879	-23.0826	30.08294
482c9d43-e1bf-474c-9ff7-4b654146632a	MLM-INFRA-0000010861	-23.0815	30.30725
62e455d0-0e46-4e6b-bd38-88cc4537890c	MLM-INFRA-0000010798	-23.0802	30.28804
9b5a648f-0f76-4f11-a972-f00a4feef7a2	MLM-INFRA-0000010747	-23.0792	30.29697
9673b1cc-4abc-42b8-a886-3044dd820891	MLM-INFRA-0000010732	-23.0787	29.95496
76177b8c-a44d-4e29-9982-541215c18f29	MLM-INFRA-0000010699	-23.0772	30.28753
21b8ea45-1106-4ccd-b204-6fb8b0881353	MLM-INFRA-0000010692	-23.077	30.35052
3451410d-025c-4392-861a-7f6a5ea5df1f	MLM-INFRA-0000010681	-23.0764	29.78597
feac6f44-4aa2-48ca-90db-52623a3e9625	MLM-INFRA-0000010674	-23.0761	30.28625

b3c0c246-bc38-44c6-8e2f-607cb2f913fd	MLM-INFRA-0000010666	-23.0758	29.84878
c0b468fb-3e97-45b8-b9b4-ed273c87c538	MLM-INFRA-0000010616	-23.0736	29.61415
75ead64c-f100-45d9-a701-93216295a4a7	MLM-INFRA-0000010595	-23.0733	29.77606
002d47d5-ac0a-4f72-8c63-56ecbdf0d452	MLM-INFRA-0000010576	-23.0724	29.61827
41e14a28-9ceb-4388-bc17-35aa9cd2560d	MLM-INFRA-0000010575	-23.0724	29.61827
2c961164-54d2-4694-8cfc-2a07f74e928c	MLM-INFRA-0000010551	-23.0719	29.78482
13694998-518f-453d-870b-84e999f7bf77	MLM-INFRA-0000010544	-23.0718	29.61864
dfb96a98-cc8a-475b-a0e2-f1b24768a154	MLM-INFRA-0000010543	-23.0718	29.61864
58595922-b073-4282-bce3-b48fcea8d939	MLM-INFRA-0000010529	-23.0714	29.61905
0c57d6da-d72f-42de-bd7a-a5db2ae23dde	MLM-INFRA-0000010528	-23.0714	29.61904
f0a3142f-dedc-433c-95f2-441193788df6	MLM-INFRA-0000010515	-23.0711	30.37342
fd0c5850-3535-4f80-b4e4-3649f4e26979	MLM-INFRA-0000010514	-23.0711	30.37342
b490f6e0-0a1a-44b0-9d07-603a8720de48	MLM-INFRA-0000010511	-23.071	30.37375
08775bc1-7f86-46fd-90fa-5e12eb5ece36	MLM-INFRA-0000010510	-23.071	30.37375
0ab143db-32df-4601-ab23-f280f9e0a042	MLM-INFRA-0000010500	-23.0707	30.37392
bdd236da-82f5-4d5f-90df-94ee6018e8d6	MLM-INFRA-0000010457	-23.0701	29.87614
3135e177-4548-427b-a66f-9b6cad1de242	MLM-INFRA-0000010455	-23.0701	29.62007
6e0b8bf5-0a8a-48d9-9ac7-85c5072bf70e	MLM-INFRA-0000010454	-23.0701	29.62007
f429b59e-85d7-462b-b8ec-59dcc652c9c6	MLM-INFRA-0000010409	-23.0694	29.87675
b0a808c6-53db-41fa-901f-2bea9126030e	MLM-INFRA-0000010405	-23.0693	29.62045
4ea43746-aa5f-4d37-8e44-b7618fd03e1d	MLM-INFRA-0000010404	-23.0693	29.62045
41c8f20d-18c5-4072-ae83-db9b1a41b962	MLM-INFRA-0000010399	-23.0692	30.3801
bd2d0d3c-d7ea-498b-9c59-89bb1981d80f	MLM-INFRA-0000010397	-23.0692	30.3801
a7ada0e4-9d25-4e79-a60d-a48e632d8049	MLM-INFRA-0000010380	-23.0688	29.62071
32e75e8e-73e9-4ffd-b87e-11c3363f82cf	MLM-INFRA-0000010379	-23.0687	29.62072
f2e534e5-577d-496f-b44d-9e02f9b6fb64	MLM-INFRA-0000010373	-23.0687	29.91265
b52537f5-e5e8-4c50-9bc1-597592391713	MLM-INFRA-0000010251	-23.0671	29.93072
0fc05ab1-ac57-419a-8a26-b5b99c4977e5	MLM-INFRA-0000010244	-23.0676	29.62131
e7f02660-782d-41fb-97f9-ac752ffc69d1	MLM-INFRA-0000010243	-23.0676	29.62132
3d7a1cd6-4db9-498f-a9ca-940a408e908a	MLM-INFRA-0000010172	-23.0659	29.88108
82ef5e8a-1022-47b0-b848-05a6c73f5b97	MLM-INFRA-0000010163	-23.0657	29.8758
c91973f6-c19a-4cb7-a142-9de1cebf7099	MLM-INFRA-0000010152	-23.0657	29.59708
50fa9cb4-ecfb-45ff-abdf-2bbb31c3b50d	MLM-INFRA-0000010115	-23.0652	29.62261
b36f9d80-46f6-4dcf-a600-9bbe47d903a8	MLM-INFRA-0000010114	-23.0652	29.62261
828e387a-aa4f-462d-a5ac-c565a57b7f24	MLM-INFRA-0000010091	-23.0647	30.37229
03a97bc0-8f67-4c60-894c-28c8a61b912e	MLM-INFRA-0000010090	-23.0647	30.37229
6e891c60-a068-49a2-812f-a46c0069a825	MLM-INFRA-0000010082	-23.0646	29.88501
fdb39d1f-0ff9-4f3e-9408-d77c74db6517	MLM-INFRA-0000010037	-23.0639	29.62325
872a4cd5-2ab1-4b7a-b068-c2197c7a8eac	MLM-INFRA-0000010036	-23.064	29.62322
a55f44a3-7870-4889-b0cc-9dbbcd8cdc74	MLM-INFRA-0000010034	-23.0639	29.87976
0aae5fe7-6778-40c4-ad83-cc4ce2ea58fc	MLM-INFRA-0000010026	-23.0636	29.91084
b6db4fa4-4773-4ffd-bc94-18b8235ac794	MLM-INFRA-0000010024	-23.0638	30.37199
6b7423a0-eea2-4ded-9a09-f2976c46c2d9	MLM-INFRA-0000010023	-23.0638	30.37199
5e35ec9c-2e05-4c01-b39f-0216e2ea237a	MLM-INFRA-0000009959	-23.0632	30.0622
75e8bd77-cb0d-4754-90d9-fba3bae5b621	MLM-INFRA-0000009908	-23.0627	29.88949
25416b9d-5dcb-48e0-8e3d-851f687a7321	MLM-INFRA-0000009903	-23.0626	29.93029
7b14ea29-1e79-4984-9c74-5264029f4fe8	MLM-INFRA-0000009833	-23.062	29.62908
56e48e48-d971-4701-a3cb-dabea7fdd78a	MLM-INFRA-0000009832	-23.062	29.62908
aea2c5b6-26b1-4f3e-8c0f-256947c609b5	MLM-INFRA-0000009797	-23.0618	30.37135

b8361c48-cc1b-4a94-8b2b-d4b89a6bc5d9	MLM-INFRA-0000009796	-23.0618	30.37135
60143933-8cf4-48bb-9807-52336f44be15	MLM-INFRA-0000009791	-23.0618	30.37135
6124c022-f146-41c8-ac3f-1ab11a065e46	MLM-INFRA-0000009689	-23.0608	29.88315
a1d65465-5dd7-4eaf-b36f-dca17ecb2708	MLM-INFRA-0000009646	-23.0612	29.91146
13ac944c-fd51-4f75-a75f-b6501dcc169d	MLM-INFRA-0000009624	-23.0602	29.91611
f71b4018-60cf-4f17-8ba1-cd75627621a9	MLM-INFRA-0000009473	-23.0586	29.90495
4f74b831-2a17-424e-b05a-4c88340b886e	MLM-INFRA-0000009342	-23.0568	29.90657
6db36c88-e888-4410-89f1-59dd20b9cad7	MLM-INFRA-0000009341	-23.0568	29.90657
b0223e10-a66d-452f-8ba1-84c8484ab4ee	MLM-INFRA-0000009340	-23.0568	29.90657
246a9b33-9f4b-4b35-a36c-4a87272f509c	MLM-INFRA-0000009322	-23.0567	29.9277
2bcf0355-b460-463c-8885-61ab6037db65	MLM-INFRA-0000009285	-23.0576	29.89674
b857ad3c-167b-429c-8968-57aca2caf42e	MLM-INFRA-0000009283	-23.0577	29.89667
6fa5528c-2f65-4ea4-951e-43c0228cfc0c	MLM-INFRA-0000009257	-23.0564	29.92767
75c7313d-31b8-4a68-9683-e2b064464585	MLM-INFRA-0000009255	-23.0562	29.92454
782517b7-62f2-4653-8bb9-62b8935bf903	MLM-INFRA-0000009253	-23.0564	29.92527
60d9eb9a-e4f1-45da-923f-26d00f9b7622	MLM-INFRA-0000009248	-23.0563	29.90496
527b484d-56bb-4a88-81cd-be7f2b9ea36d	MLM-INFRA-0000009247	-23.0563	29.90496
040b5d80-c6bf-4c44-b2cb-e0891e324e40	MLM-INFRA-0000009246	-23.0563	29.90496
c958c53d-2203-48bb-a82d-4bb585934a1d	MLM-INFRA-0000009232	-23.0528	29.92652
fb8706ac-6ee0-4f95-8f79-15280037e5ee	MLM-INFRA-0000009216	-23.056	29.90398
3c7cd003-e328-4f27-b24c-59bb674dfb4a	MLM-INFRA-0000009173	-23.0558	29.90427
036da566-70a3-4626-92a2-cff77407684e	MLM-INFRA-0000009156	-23.0554	29.90271
18d058f1-4885-4b9f-b1ea-2b608538281c	MLM-INFRA-0000009137	-23.0556	29.90331
777e705c-a41a-4f9a-8ba9-f7daaa2fcfdc	MLM-INFRA-0000009136	-23.0556	29.90331
3059ee57-9e95-4002-be12-34ecc60c6cbf	MLM-INFRA-0000009135	-23.0556	29.90331
477c3ca7-05e5-49c9-a056-5848997fbc34	MLM-INFRA-0000009124	-23.0552	29.90243
ec4c16bc-2435-49e3-90e2-fcd1133fc0e9	MLM-INFRA-0000009095	-23.0554	29.90242
5803ba37-e5fe-40ff-9106-03022e547e0e	MLM-INFRA-0000009081	-23.0554	29.92509
5131f41a-1cbe-49a3-9d23-2d965df289a0	MLM-INFRA-0000009056	-23.0553	29.92586
b5e284bf-b8d5-41e3-aa2e-7470fac77381	MLM-INFRA-0000009039	-23.0552	29.90866
9c9e2659-3645-431d-857e-6d48a555ec45	MLM-INFRA-0000009036	-23.0551	29.90176
174ebf64-2a3b-475d-a56c-619ad0bc362f	MLM-INFRA-0000009035	-23.0553	29.90859
6e5ef383-f663-4438-b691-f4cdf73b0cbd	MLM-INFRA-0000009021	-23.0551	29.90182
1e1d47bf-2e94-4551-8380-fd1334830b07	MLM-INFRA-0000009020	-23.0551	29.90183
56c93a8a-0740-49b0-a6a7-f70e0b4dd1c6	MLM-INFRA-0000009019	-23.0551	29.90182
5504e7fe-5d0e-4971-a7d1-d18a68157dc4	MLM-INFRA-0000008997	-23.0549	29.90462
3989ab8f-5096-401d-a86b-187dd819854e	MLM-INFRA-0000008996	-23.0549	29.90462
f2d44e05-e5d6-4958-9b17-343c05b822d4	MLM-INFRA-0000008995	-23.0549	29.90462
f2eb2b5c-6029-43eb-b988-f58464b13b1d	MLM-INFRA-0000008993	-23.0548	29.62682
0841069a-fc20-4b7d-a67c-8cabb97ae4d6	MLM-INFRA-0000008992	-23.0548	29.62682
439eaa23-9aba-4820-8724-271f1c3ec25e	MLM-INFRA-0000008990	-23.0548	29.90113
94b287ad-1e02-4357-ad6b-f74d2459eff4	MLM-INFRA-0000008954	-23.0547	29.92333
ed79ebc0-7da1-4b24-9108-55c1bc732718	MLM-INFRA-0000008952	-23.0548	29.90651
93d2df44-4882-4a9f-ae77-49de88712ddc	MLM-INFRA-0000008878	-23.0551	29.9259
fb5cb0b0-5899-4b3a-b178-e709868ca819	MLM-INFRA-0000008864	-23.0542	29.92535
3b492677-e0c9-43f0-b818-7ea9d98aa5c2	MLM-INFRA-0000008856	-23.0542	29.91794
3edaf7b8-5b35-4e50-af20-6887a21dcb32	MLM-INFRA-0000008853	-23.0539	29.92283
2e425588-28cf-4f04-8371-c90eebf84e8c	MLM-INFRA-0000008846	-23.0541	30.30455

735c697e-94f9-43ef-a6bc-4caa76506053	MLM-INFRA-0000008821	-23.055	29.90179
13218b52-534f-41eb-8083-df7953657820	MLM-INFRA-0000008774	-23.0538	29.92942
d09e67f6-851e-4f91-9082-72505d5c5b54	MLM-INFRA-0000008748	-23.0536	29.92378
529321ae-a9aa-4959-aaeb-760bea142059	MLM-INFRA-0000008732	-23.0536	29.92184
14537a87-f8a4-4106-92cc-fa49fa366bdd	MLM-INFRA-0000008717	-23.0536	29.9203
5d3c733d-21d2-4137-8fda-ec27f42f4da2	MLM-INFRA-0000008712	-23.0542	29.92422
301d0440-2a48-4858-afeb-4b44e888deac	MLM-INFRA-0000008711	-23.0535	29.92199
abe758c2-1805-4074-bec1-9328cc8c0649	MLM-INFRA-0000008705	-23.0535	29.9211
b38144b0-bea6-4784-907e-ad7ebc8d086c	MLM-INFRA-0000008702	-23.0535	29.92033
248cfc3d-3128-4857-b7c6-21ad5dfc2230	MLM-INFRA-0000008689	-23.0535	29.92092
ab110cb1-ba82-471e-9d1e-bc6525640798	MLM-INFRA-0000008686	-23.0535	29.92072
f74f5c84-8541-4fe8-93c6-98d47547dab9	MLM-INFRA-0000008680	-23.0534	29.92226
e8296b24-b857-4e62-b09e-b7a75dbb9a98	MLM-INFRA-0000008678	-23.0534	29.91906
5ee8977b-7a25-4766-b88a-84e4d5e9834b	MLM-INFRA-0000008671	-23.0534	29.92223
3067b48a-6ee2-43a6-a89a-e83e5bbac6c3	MLM-INFRA-0000008665	-23.0534	29.92237
25eb4136-4a06-466f-977f-8bb5d5fe3bdc	MLM-INFRA-0000008640	-23.0533	29.92252
fb63f43d-f1aa-4207-980e-ca6eb0814918	MLM-INFRA-0000008636	-23.0536	29.91634
2a2ebb08-510c-4cf0-aec7-452307789794	MLM-INFRA-0000008635	-23.0533	29.92243
59fa8ba0-e331-4ffe-ae17-473b54537eef	MLM-INFRA-0000008625	-23.0532	29.92032
17caa372-9121-4dde-81b4-497bc8da66c4	MLM-INFRA-0000008586	-23.0529	29.92564
92091fc5-3e30-4d77-82d8-98e87c716dc4	MLM-INFRA-0000008585	-23.0529	29.92027
f837ce32-84ba-4191-ab83-9c4a70f991e9	MLM-INFRA-0000008555	-23.0528	29.92214
656cf896-199d-4b61-a210-4c2241ee4720	MLM-INFRA-0000008553	-23.0528	29.92192
a2dc1be3-eab3-4fb9-808f-ab4efe650f1b	MLM-INFRA-0000008551	-23.0528	29.92225
effd3665-d977-4424-85d2-e2015b3f2b3a	MLM-INFRA-0000008522	-23.0527	29.92205
7f0c79fa-728c-49e6-a7c6-2ddd0c56c511	MLM-INFRA-0000008515	-23.0526	29.92207
8cc48e26-0674-4a9e-9a9f-edf6fbd3d6cf	MLM-INFRA-0000008506	-23.0526	29.92206
bb5abc45-2cb4-4f46-af9d-b1a99f8c2e4a	MLM-INFRA-0000008417	-23.0521	29.9261
d551b1c1-3629-45bf-87b2-b12a7e2bd965	MLM-INFRA-0000008406	-23.0521	29.90517
4076e418-237f-401e-a2c8-0dc57549990	MLM-INFRA-0000008401	-23.052	29.92598
2a52247a-bb29-4f1c-804b-ef9f90aca773	MLM-INFRA-0000008400	-23.052	29.92438
1043b876-c35c-4326-8106-2097fa946a4a	MLM-INFRA-0000008393	-23.052	29.92443
9b5a5f98-038b-4bf9-b1fb-dc080cebcd59	MLM-INFRA-0000008388	-23.0519	29.91332
b65f6325-c475-4e5f-b163-0e6a4efad6c6	MLM-INFRA-0000008373	-23.0519	29.92405
11b81e40-c7b1-4b4a-9736-47236b714189	MLM-INFRA-0000008348	-23.0518	29.92184
95bb0b74-da97-4841-bb79-d54a09b035a2	MLM-INFRA-0000008347	-23.0518	29.92201
8d83918f-bd91-41a8-8a37-1228bc6d6292	MLM-INFRA-0000008346	-23.0519	29.90592
39235ef9-b895-48fa-a7ec-d1dab9fa949d	MLM-INFRA-0000008327	-23.0517	29.92193
ee361132-e46e-4295-bce1-e69568f013d5	MLM-INFRA-0000008324	-23.049	30.36055
d558ec32-32c1-4701-a56e-b100ae67ac45	MLM-INFRA-0000008313	-23.0519	29.91345
8ca94892-6a09-4296-bc80-accebca5770a	MLM-INFRA-0000008308	-23.0519	29.9053
e12f6070-bead-4b0e-960f-57c8ca52e39a	MLM-INFRA-0000008289	-23.0516	29.90596
87787806-3e70-4195-ad07-b7a8be596b29	MLM-INFRA-0000008241	-23.0517	29.90586
23905f11-c362-4a0f-9fc3-92c63645ad8c	MLM-INFRA-0000008209	-23.0513	29.92553
c3bd134a-e12c-45a5-b41c-34bb7fabe2cb	MLM-INFRA-0000008202	-23.0514	29.90524
48608c8e-12a2-4048-884c-3427a0025090	MLM-INFRA-0000008201	-23.0513	29.92662
ecaf552d-06cc-48b2-b5a7-4fd0ed5f8958	MLM-INFRA-0000008185	-23.0512	29.92377

ebd5cc13-06cb-4c91-a214-824e66993f46	MLM-INFRA-0000008177	-23.0511	29.922
1ad86be4-694c-4b9e-8723-6f0545e84fbd	MLM-INFRA-0000008145	-23.0516	29.90616
802fe7ab-9228-443c-bb0c-45ee19bfd51e	MLM-INFRA-0000008132	-23.051	29.92199
299b9491-36e4-4db6-ab16-88fdced3d08	MLM-INFRA-0000008122	-23.051	29.91392
19a05ff0-6de3-4e1f-8c26-446a705c2d7e	MLM-INFRA-0000008073	-23.0507	29.91924
387f7856-4211-42da-8c51-e67ae3c0ac0b	MLM-INFRA-0000008063	-23.0518	29.90606
1cf39637-8c2a-4dd7-b3c3-f6edd3764d33	MLM-INFRA-0000008060	-23.0508	29.91967
2d123d58-b198-49a1-8722-e7930168cd3a	MLM-INFRA-0000008059	-23.0507	29.91957
9d8f2222-cf9b-43a2-9089-ba0436cb9157	MLM-INFRA-0000008058	-23.0508	29.91967
20714984-9a23-4ae8-81c7-108b59244e73	MLM-INFRA-0000008042	-23.0504	29.91807
37050afd-dbec-46de-849f-dad14960dbfb	MLM-INFRA-0000008026	-23.0506	29.90654
532d28bc-47f4-496c-a104-86a890c24fcc	MLM-INFRA-0000008019	-23.0505	29.91846
eb686128-94a7-4324-8f27-92d5b5e8687a	MLM-INFRA-0000008014	-23.0505	29.91849
58aa51e3-df19-44f9-bb2d-773c40a85316	MLM-INFRA-0000008003	-23.0506	29.9029
48fb46e5-4bc4-4dd1-a76a-b23e929c1c9c	MLM-INFRA-0000008000	-23.0505	29.91905
221092a6-5033-4d80-ae1c-53c411f49f71	MLM-INFRA-0000007990	-23.0505	29.91847
ae765f89-3054-49e3-bece-deb7a4364f83	MLM-INFRA-0000007984	-23.0505	29.91808
bcde5295-fb3c-4309-afe4-411ce3d339ab	MLM-INFRA-0000007959	-23.0504	29.91743
1e3c79b4-773e-4bd5-b225-fae0be93a6c7	MLM-INFRA-0000007958	-23.0502	29.91723
664091ea-7a0e-4683-8c31-ce68a7ef13df	MLM-INFRA-0000007943	-23.0505	29.90649
176080b3-c28b-45a7-a9be-2e6e280ffe79	MLM-INFRA-0000007928	-23.0503	29.91741
4cc3097f-018d-4f32-b99b-df30a920a9dd	MLM-INFRA-0000007918	-23.0503	29.90238
bc2cc759-56fe-4ff9-ae7c-074e0d82f6b6	MLM-INFRA-0000007914	-23.0502	29.91723
bf0e62ca-58a0-4db7-ab7c-f188c5702008	MLM-INFRA-0000007912	-23.0504	29.91743
73fb2d42-6e71-4f56-9728-dfdd1d3b352e	MLM-INFRA-0000007895	-23.0504	29.91783
eeff19bb-1400-4769-bcf3-022968fe97b1	MLM-INFRA-0000007892	-23.0504	29.90653
4b870f2b-9765-4a6d-884f-51b3841abe80	MLM-INFRA-0000007885	-23.0501	29.91055
b07bb900-0d33-463b-8789-a15c28954689	MLM-INFRA-0000007839	-23.0499	30.30352
a019fb4a-7420-4067-a368-5606073ccb8c	MLM-INFRA-0000007742	-23.0495	29.91267
af3e96bd-79c5-4fb2-a99e-c2be28ed7d2d	MLM-INFRA-0000007718	-23.0494	29.89949
f54b2e45-1e42-48eb-82dc-0c72acb22a79	MLM-INFRA-0000007648	-23.049	30.36055
61f2d6ee-6e29-4c15-8895-4dff95bb8f8b	MLM-INFRA-0000007647	-23.049	29.89982
2db424d1-45a8-4e14-90ca-f9bcadf6052d	MLM-INFRA-0000007620	-23.0488	29.91117
26c8a52d-aea2-4c8d-b394-d62a909b6b88	MLM-INFRA-0000007562	-23.0487	29.89811
fd2c5d13-8740-4a66-af56-6b33fc7b1118	MLM-INFRA-0000007526	-23.0488	29.90549
2a020cf5-589e-4405-be68-f405d33b6114	MLM-INFRA-0000007503	-23.0485	29.90744
0ea1aff5-ac37-4ba5-ae42-23cfec321617	MLM-INFRA-0000007502	-23.0485	29.90744
676a81c6-6471-45f7-aa15-8ba69cbdf45	MLM-INFRA-0000007463	-23.0481	29.91804
337b194c-5aad-4fab-a7f2-710a09b73022	MLM-INFRA-0000007441	-23.0473	29.91794
3c6cd4e4-6df0-4090-8592-fabe56743ed8	MLM-INFRA-0000007416	-23.0482	29.90017
23fd7a18-b4a3-45a5-86f6-726fdbbaa9d3	MLM-INFRA-0000007362	-23.048	29.89611
e0202291-0232-4e2b-8f63-f5a47b87024e	MLM-INFRA-0000007330	-23.0479	29.88906
c37f0306-110c-4453-a333-d05891b94086	MLM-INFRA-0000007306	-23.0479	29.88908
3de0a1c8-008c-4f13-b9c8-3d50ea647edc	MLM-INFRA-0000007281	-23.0477	29.90214
ad6c99f4-5fee-480d-9360-1bfb75f36c47	MLM-INFRA-0000007221	-23.0476	29.90782
bd59b20c-a604-4d66-bb7c-a95d76c3bd34	MLM-INFRA-0000007213	-23.0475	29.89495
1b721241-8728-47c4-9caf-0dc966e1afbe	MLM-INFRA-0000007152	-23.048	29.90024
070e17f9-5d03-4319-8eb3-6b56b048a82b	MLM-INFRA-0000007146	-23.0475	29.90776
031849ca-d69b-4fe6-a883-c82426efda14	MLM-INFRA-0000007123	-23.0472	29.88759

63d6ea21-636a-497d-90d4-32cce74ce570	MLM-INFRA-0000007059	-23.0469	29.88006
213616d7-6de5-49d6-b790-d7226de4ea2b	MLM-INFRA-0000007034	-23.0468	29.89155
098f9795-35f4-482a-9a32-c7afb3f86cea	MLM-INFRA-0000007018	-23.0467	29.89333
285fc59a-099f-4b61-8203-fb5b9778c373	MLM-INFRA-0000007015	-23.0466	29.92212
cb808df6-58eb-46d1-897c-573e306f6403	MLM-INFRA-0000006988	-23.0466	29.92212
a4b8eae5-c668-4235-af91-d84efef2aaf7	MLM-INFRA-0000006975	-23.0466	29.89251
fbaa09bc-7846-4a41-850c-5ca85e20d090	MLM-INFRA-0000006965	-23.0466	29.89896
e129057b-9005-4e03-be62-0a00314dca3e	MLM-INFRA-0000006942	-23.0539	29.90497
bec1abcf-35d1-427b-b3f1-1185f3a0de17	MLM-INFRA-0000006935	-23.05	29.86897
96c1f56f-54b3-493c-b5b4-0dc61704c7cf	MLM-INFRA-0000006889	-23.0464	29.92264
e562bc97-f3de-4712-8274-790d05439f33	MLM-INFRA-0000006884	-23.0464	29.92264
63ae5c6b-5a63-4763-a536-eccdb8c5ec02	MLM-INFRA-0000006863	-23.0463	29.89174
839e4b23-c7b2-4c35-9f3f-6056b66000f1	MLM-INFRA-0000006851	-23.0463	29.92264
02d9fd3b-fb1d-4385-9d40-49152821771b	MLM-INFRA-0000006843	-23.0463	29.92226
0d8a50c7-029f-41c3-8199-b476f5759bf5	MLM-INFRA-0000006832	-23.0463	29.92226
4eec592e-8185-45f8-a150-f11ab0523740	MLM-INFRA-0000006828	-23.0462	29.89736
9adf1103-d521-4bda-aa93-23f8301520f4	MLM-INFRA-0000006806	-23.0461	29.92209
efdcf1c1-da44-4605-b779-4801d056ea8c	MLM-INFRA-0000006767	-23.046	29.92193
5d5b5685-cd65-4755-bb17-13ba65d04e25	MLM-INFRA-0000006744	-23.0449	29.92084
dc9972c6-2fe7-4700-8cd4-faf8d1865775	MLM-INFRA-0000006739	-23.0459	29.89008
1462d8cc-8e66-439f-9b94-d159b737f95d	MLM-INFRA-0000006706	-23.0461	29.92209
15d0b68e-c2e0-45c3-a2b7-feed1f585b01	MLM-INFRA-0000006681	-23.0465	29.89909
1e071c3f-75b9-4840-88d3-2a9dbb17c1aa	MLM-INFRA-0000006599	-23.0456	29.92191
c0d9893c-7a44-4a0a-9e55-4c34dcd481b7	MLM-INFRA-0000006593	-23.0455	29.90304
05083d4e-58c0-46bd-8726-5320ddece5ea	MLM-INFRA-0000006566	-23.0456	29.92191
aab52cb8-edda-4b7b-af23-db6165772efe	MLM-INFRA-0000006553	-23.0454	29.92184
10c57baa-a2fb-4488-aac4-0ab9202c038f	MLM-INFRA-0000006546	-23.0455	29.88008
ee708558-3310-4f83-b5b9-6301f2a1728a	MLM-INFRA-0000006545	-23.0454	29.89568
22681a05-cad6-429b-af40-552f6f50b2ee	MLM-INFRA-0000006524	-23.0453	29.89573
aeabb936-f86b-4367-8377-d90277a3cce2	MLM-INFRA-0000006522	-23.0453	29.87873
d9a9caaa-c670-4e44-b3d9-b54bac24d179	MLM-INFRA-0000006394	-23.045	29.91379
41ab70f5-5712-487a-95f3-eeb888d33de0	MLM-INFRA-0000006382	-23.0455	29.89583
a242608c-cac6-4023-8a9a-5f001df6539e	MLM-INFRA-0000006260	-23.0441	29.91914
8e0bf83d-fa90-43a3-81f2-7b75ef1cc47d	MLM-INFRA-0000006127	-23.0443	29.87515
06d4f80d-968c-430e-8c2b-da931bdf3d7b	MLM-INFRA-0000006101	-23.0441	29.92153
4bad5c28-97b7-420b-a4a6-6095abd31150	MLM-INFRA-0000006100	-23.0441	29.89252
3c480f58-506f-44a1-85c7-a98bfef1e888	MLM-INFRA-0000006066	-23.0444	29.90185
d91c0ae4-b88d-40c6-971e-e868967c08a2	MLM-INFRA-0000006013	-23.0439	29.89822
c0de259c-b62d-4d44-9378-ea2681817c4f	MLM-INFRA-0000005989	-23.0437	29.91816
6394189b-8c2e-4ba8-ad3d-62563edb0eba	MLM-INFRA-0000005917	-23.0435	29.90996
fc0eadbe-786f-481c-90b7-59f3b3f01449	MLM-INFRA-0000005916	-23.0434	29.90998
3f969518-83d8-4871-bc1b-ca35d1a1bfcb	MLM-INFRA-0000005914	-23.0435	29.89113
d1351125-b7d5-4f29-a444-b0971d25310e	MLM-INFRA-0000005843	-23.0434	29.90989
c371e90c-4f83-4843-9a86-2f76eb17148e	MLM-INFRA-0000005667	-23.0428	29.9025
ce1d2807-d300-414a-9fc3-7c08d4b4d796	MLM-INFRA-0000005632	-23.0427	29.89497
88602e61-7d8b-4018-93f6-9882a465b164	MLM-INFRA-0000005496	-23.0422	29.91817
4bcb9648-98f0-4201-a6cc-f8e5de0df6fd	MLM-INFRA-0000005460	-23.0423	29.90083
34a3051b-f235-47b4-bb19-0660ab84bddc	MLM-INFRA-0000005433	-23.0421	29.90003
a084c8de-bf88-4380-8efc-c800033f2596	MLM-INFRA-0000005343	-23.0419	29.9218

6f0ec8ed-6b4d-4ad1-aafe-754bc7dea890	MLM-INFRA-0000005342	-23.0421	29.90087
9f1ec140-6c4b-4455-befd-4221c473bdcd	MLM-INFRA-0000005201	-23.0416	29.90497
26f58092-2941-4d95-bd0b-93ed1497fe80	MLM-INFRA-0000005181	-23.0415	29.90513
aff99bf0-5b48-425b-93be-81ef421f818c	MLM-INFRA-0000005061	-23.0411	29.90887
03e875ae-747b-4950-9802-9440f5425d9d	MLM-INFRA-0000005013	-23.041	29.89768
78d1ef43-a0a8-48a6-a6c8-e3a038423ec0	MLM-INFRA-0000005012	-23.0405	29.89594
04c88def-e0f9-46b4-951e-d5155e651700	MLM-INFRA-0000004979	-23.0409	29.91087
d3db8bc6-29b5-4a57-ac4c-4ec7806572fc	MLM-INFRA-0000004947	-23.0408	29.92405
71ca5f8f-010e-4dfc-90d6-ec8f21aea018	MLM-INFRA-0000004905	-23.0407	29.92304
2a0a7f5d-8067-4b8e-88c9-af91a4a0cf3f	MLM-INFRA-0000004887	-23.0407	29.91826
0c85486f-482b-4f3a-9a98-252a4b5af976	MLM-INFRA-0000004854	-23.0405	29.91825
7d99e507-ae6b-4568-9722-ede293700f40	MLM-INFRA-0000004816	-23.0402	29.92128
c4f1577a-484f-4701-bf42-b13e14f9625e	MLM-INFRA-0000004808	-23.0401	29.90183
56185c7c-1676-425b-92e5-348cb3714d23	MLM-INFRA-0000004648	-23.0397	29.90741
134a8d75-c675-4a1e-9c3f-3862711af972	MLM-INFRA-0000004644	-23.0398	29.91122
e9ddd735-406f-48b9-a31d-3f86fdc34244	MLM-INFRA-0000004617	-23.0394	29.92406
1493c6a0-fccc-40a7-b2b8-488b315c09f9	MLM-INFRA-0000004583	-23.0394	29.92345
efbea86e-2337-4243-88b4-4f3e61b973ec	MLM-INFRA-0000004564	-23.0394	29.91523
cbfe2a8d-a8b7-4e90-8283-c2bacd086e3e	MLM-INFRA-0000004561	-23.0441	29.92175
ba6f3710-7bb5-40c4-8287-b9e9c95b4889	MLM-INFRA-0000004525	-23.0427	29.92171
7ab407b3-fe53-406d-9213-f89f9a55dc1a	MLM-INFRA-0000004522	-23.0392	29.91955
076d3ef2-8301-4943-a002-542040f59414	MLM-INFRA-0000004520	-23.0392	29.91961
caa8e55e-6af4-48c2-a5cf-9cc927b6e7ee	MLM-INFRA-0000004518	-23.0393	29.91941
a6964ffd-2315-45e2-ada5-c8563b79d0cc	MLM-INFRA-0000004501	-23.0392	29.9212
339dc16b-b863-44c1-aac4-d9d1288dbe58	MLM-INFRA-0000004487	-23.0392	29.91975
449ea813-f554-4476-ad52-b8affab76048	MLM-INFRA-0000004457	-23.039	29.89868
b9639f08-0b21-4145-86c3-70f4652f997c	MLM-INFRA-0000004423	-23.0387	29.90998
1c20f9b4-9789-4472-bba1-7a9c841b14b1	MLM-INFRA-0000004265	-23.0441	29.92161
0fcca60-06e5-4545-aa80-a3e2a81b8e2a	MLM-INFRA-0000004256	-23.045	29.9209
3350185a-0ac5-4671-a346-e51bcf057fab	MLM-INFRA-0000004236	-23.0379	29.9018
bb5ce877-3db3-4240-a8a9-d3d5ecfb38e7	MLM-INFRA-0000004226	-23.0446	29.92029
5175927b-2f9a-4480-8a00-052b755cd577	MLM-INFRA-0000004215	-23.0376	29.91924
901bd66a-d828-4159-85e4-62349e700a9d	MLM-INFRA-0000004185	-23.0375	29.90398
28143269-c714-44c1-aac0-0512b59b0a3f	MLM-INFRA-0000004078	-23.0369	29.9257
474ce8c3-7cf0-4701-bf1e-84bc0a2b9334	MLM-INFRA-0000004077	-23.0369	29.9257
ea3a6e3d-e74c-4051-ab51-82fe212c5813	MLM-INFRA-0000004076	-23.0369	29.9257
f206d80d-c802-4b1e-b0dc-cf8300fef67d	MLM-INFRA-0000004071	-23.0368	29.92748
4e97e93c-f375-4f1a-a530-643dbdbcf576	MLM-INFRA-0000004066	-23.0369	29.92361
792ccce5-5ed3-4a9b-9976-a134f3e2f47b	MLM-INFRA-0000004065	-23.0369	29.92361
2e6bfacd-1fc0-4592-9e81-954b910a43e9	MLM-INFRA-0000004063	-23.0368	29.92748
efb624b4-fd37-4989-88e1-0da38c3fce40	MLM-INFRA-0000004062	-23.0368	29.92748
d570093a-246e-4522-a235-f04328e8a579	MLM-INFRA-0000004057	-23.0369	29.92361
ba9b77a4-27b9-48e3-bc4c-0e327c8d4375	MLM-INFRA-0000004054	-23.0368	29.92833
7cca931e-376f-402a-8177-3052b4667fb7	MLM-INFRA-0000004053	-23.0368	29.92834
f0dd7fa4-b71e-465d-97df-8939d9ddef5d	MLM-INFRA-0000004045	-23.0368	29.92835
98e769de-7251-44f7-a3dc-46faf6852be6	MLM-INFRA-0000004039	-23.0368	29.92244
6e8a0843-a236-46f7-8bb3-70ba662b83e6	MLM-INFRA-0000004037	-23.0368	29.92244
cd78b9f8-e5b7-4def-a0b5-991c26ecc575	MLM-INFRA-0000004036	-23.0368	29.92244
f4e1b940-954f-42cc-ac17-e34bcb861beb	MLM-INFRA-0000004006	-23.0429	29.92188
8849a996-f185-4f3d-bda1-f9ce4fa588b3	MLM-INFRA-0000003904	-23.0359	29.9281

d515528e-99bd-45c1-99b6-2db123402499	MLM-INFRA-0000003898	-23.0359	29.92813
4437cd8e-790c-46b7-b9a3-6c4cfc5beb62	MLM-INFRA-0000003879	-23.0359	29.91901
51b02c90-29aa-4b0b-8426-cbb28f4c22a9	MLM-INFRA-0000003873	-23.0359	29.9281
7b13a6b7-8ff0-4564-8f4e-9ccd5e601121	MLM-INFRA-0000003757	-23.0351	29.90953
3fd013c8-aaed-4692-bedf-d371023ba3bb	MLM-INFRA-0000003706	-23.0351	29.91864
4242e49b-837c-425b-845e-4fd99ebc5349	MLM-INFRA-0000003659	-23.0346	29.91307
55ad448b-0e64-4300-87af-e84861ffd6c9	MLM-INFRA-0000003613	-23.0348	29.92813
07eb45fe-ec83-497c-a81e-ed8f2587f30b	MLM-INFRA-0000003585	-23.0342	29.92844
ec3c1cc2-c923-44b7-8a2b-f73059357d49	MLM-INFRA-0000003575	-23.0342	29.92482
a6a1ee7a-826d-4652-886b-db456539eaa3	MLM-INFRA-0000003574	-23.0342	29.92844
9a767af8-6f45-4fde-ab5f-e00e022abe8a	MLM-INFRA-0000003572	-23.0342	29.92844
ce8195ed-e658-4b4e-a8f7-3981887b7b87	MLM-INFRA-0000003522	-23.0339	29.92246
07b4c2e5-e590-471f-b8f0-b8125db8855a	MLM-INFRA-0000003516	-23.0351	29.91864
e062fb26-1fc8-47e0-820e-4b8f98ec9a4a	MLM-INFRA-0000003460	-23.0308	29.92961
d5f01dcb-2f14-447b-bed3-4dab6855f536	MLM-INFRA-0000003386	-23.0335	29.92856
a074c977-9107-46e0-8c2e-76b33e4a73f8	MLM-INFRA-0000003374	-23.0322	29.92918
31a6099d-1bf7-4e22-8d11-f03e642a13d6	MLM-INFRA-0000003360	-23.0329	29.92886
e8c53ce1-38b2-4cc3-8dae-9499059e8e84	MLM-INFRA-0000003354	-23.0329	29.92886
edbbcb82-d779-4597-ad5e-135c2b346ef3	MLM-INFRA-0000003351	-23.0329	29.92889
e37d2bfd-e66a-45a0-9e3d-037ee82d4f0d	MLM-INFRA-0000003339	-23.0429	29.92092
9c7718da-a26f-4882-948a-b1eef7369694	MLM-INFRA-0000003318	-23.0321	29.92912
61e9eb34-a967-4398-8033-919d2b46995f	MLM-INFRA-0000003268	-23.0327	29.92026
3aa27dc9-8b88-4930-bcff-5401917192f3	MLM-INFRA-0000003267	-23.0327	29.92477
6d1b791c-3ed4-475f-936a-414d848f8d65	MLM-INFRA-0000003261	-23.0328	29.92476
0ba3956f-b6cc-4ead-b4e1-6f1f43daf5d7	MLM-INFRA-0000003259	-23.0328	29.92477
204c9b12-14d7-400b-9986-e81f2ea6e7f1	MLM-INFRA-0000003156	-23.0316	29.92937
cb8e7704-7360-4923-91de-79d2648cd58b	MLM-INFRA-0000003155	-23.0316	29.92938
ba86838a-22bc-4d03-80d3-746a49a50e59	MLM-INFRA-0000003150	-23.0316	29.92937
39fa1ea9-f7ad-4c96-bfae-b1bc350f57e0	MLM-INFRA-0000003090	-23.0311	29.92958
10adda2b-a396-4271-b0ca-7aacc4eae0cf	MLM-INFRA-0000003016	-23.0305	29.92048
920e58cb-c9ff-42d2-a1e4-45db79671f92	MLM-INFRA-0000002971	-23.0304	29.92979
8487a2dc-253e-4f24-83d8-7eff14d04a79	MLM-INFRA-0000002970	-23.0303	29.92983
6c3cdfc3-104c-4c25-966e-fd62d4a3dfb2	MLM-INFRA-0000002961	-23.0304	29.9298
1d2952e7-fab4-424a-b956-e09dbc18c3af	MLM-INFRA-0000002935	-23.0304	29.92066
2a3f8c81-4ef2-4042-9e28-e603aa726b14	MLM-INFRA-0000002833	-23.0292	29.93279
16f0249c-9d44-4410-8ecd-4ada047ee2eb	MLM-INFRA-0000002827	-23.0292	29.9328
c1301c40-5913-4bc9-9063-30c73ce1e877	MLM-INFRA-0000002716	-23.0285	29.92124
1a60eec7-880c-401b-92c7-a79516f41ee9	MLM-INFRA-0000002689	-23.0284	29.92585
f97aff50-d3a7-4b36-b776-53e5dfc8e42f	MLM-INFRA-0000002604	-23.0278	29.92426
0fe78244-3df1-4877-b50f-7c15b73bf8b2	MLM-INFRA-0000002589	-23.0278	29.93025
c261e471-0c47-46b7-afc3-bce050a53c51	MLM-INFRA-0000002575	-23.0276	29.92363
a9bf93b5-9dce-4efb-9d18-5e58e0a6e620	MLM-INFRA-0000002572	-23.0289	29.92728
095ee1bc-931c-4d3f-bf17-2dafba7cdf2a	MLM-INFRA-0000002513	-23.0273	29.84657
caae1a3b-35a5-40b1-a38c-4e6b2993de61	MLM-INFRA-0000002467	-23.027	29.90929
a94fe8f8-a7f9-402c-9a02-007b41a311a0	MLM-INFRA-0000002338	-23.0261	29.85745
2d0246d3-9987-408d-82ef-8b21b6a537ba	MLM-INFRA-0000002332	-23.0261	29.91075
e6c5335a-0363-4e04-b211-bfda63429aec	MLM-INFRA-0000002222	-23.0253	29.91128

7bed3bcf-f552-4623-9ead-3fbd837dffdd	MLM-INFRA-0000002150	-23.0613	29.91515
697b9541-b5a6-4502-860a-d431bba1dcf5	MLM-INFRA-0000002116	-23.0226	30.12516
ac137187-94d5-46bf-8acc-2d9c33eadc38	MLM-INFRA-0000002023	-23.0044	29.92789
6500fa4f-9737-4b62-90bf-1344ff5e6cc3	MLM-INFRA-0000001768	-22.9727	30.07293
a11f9041-412e-4b3b-9553-7dd435c915a7	MLM-INFRA-0000001766	-22.9726	30.07258
6aa2788e-3bd5-4c9b-8306-41fcac8336ef	MLM-INFRA-0000001730	-22.9702	29.96802
6ef1a7c4-d106-458b-91a7-97edf569c536	MLM-INFRA-0000001694	-22.9617	30.21319
958748c8-0573-40c6-b954-da1458aad841	MLM-INFRA-0000001591	-22.9043	30.03016
4182e2b3-34d3-4c43-a97d-e57732dec026	MLM-INFRA-0000001584	-22.9044	30.02817
fe29095f-3101-4003-a05d-36fcd8c78e18	MLM-INFRA-0000001582	-22.9044	30.02817
2d9767c1-0e46-4ac9-92d2-ba601609481d	MLM-INFRA-0000001579	-22.9044	30.02959
36056fa2-3ded-49d3-bfbb-afb1ee6f686c	MLM-INFRA-0000001577	-22.9044	30.02959
a029b91d-b2d7-48d9-9add-705e0e4d77e0	MLM-INFRA-0000001575	-22.9044	30.02999
6526e5ef-51ce-4425-9acf-3fffddef28f3	MLM-INFRA-0000001572	-22.9044	30.02817
38bbe71d-7945-4a2a-91a4-964b703d474b	MLM-INFRA-0000001560	-22.9032	30.02667
65b1f39f-4a26-4e4e-a5f9-019fbec108f1	MLM-INFRA-0000001557	-22.9032	30.02677
c5fed5c0-cd4f-49fa-966b-49149bf11982	MLM-INFRA-0000001556	-22.9032	30.02677
679bd19a-dbfef-42a5-843b-26352330582d	MLM-INFRA-0000001555	-22.9032	30.02791
ed31c7e1-84a4-41f3-888f-1f93c6ec4282	MLM-INFRA-0000001553	-22.9032	30.02791
cd934f2c-b243-4b2a-a878-063ee5a29d39	MLM-INFRA-0000001552	-22.9032	30.02791
d69fa154-3781-4b61-8a82-bb6a3f49c9c3	MLM-INFRA-0000001551	-22.9032	30.02677
4a5898ee-bb83-4d03-a904-764af645ef41	MLM-INFRA-0000001542	-22.903	30.03035
5dd60a21-e011-4009-bcb7-c42370eb4c63	MLM-INFRA-0000001541	-22.903	30.03035
788062eb-39d3-47d1-9fd8-8cdc7285b4b1	MLM-INFRA-0000001533	-22.9027	30.02879
edd2e562-a585-4923-93ac-cdbf25e438ff	MLM-INFRA-0000001524	-22.9026	30.02882
e487f860-b4b4-4a6b-bde5-fc0aa16b6141	MLM-INFRA-0000001523	-22.9026	30.02882
f9a8e1ca-01ad-4438-8923-98fd4668db34	MLM-INFRA-0000001519	-22.9026	30.02882
aa5f13cd-4d3c-4c28-85bd-d8e5d46abcbb	MLM-INFRA-0000001474	-22.9017	30.02899
5e715ac2-3010-4a3b-8466-653a770c6157	MLM-INFRA-0000001455	-22.9015	30.02669
a0533e46-4732-4aa7-adc5-764c4ee3c4b4	MLM-INFRA-0000001447	-22.9014	30.02698
791e09e3-0bb5-4740-8c10-fcba600941de	MLM-INFRA-0000001441	-22.9015	30.02669
778c03a9-b129-4152-9625-b85c1d04a3ae	MLM-INFRA-0000001440	-22.9013	30.02784
85f45698-138a-4bfc-9eb4-34366317722a	MLM-INFRA-0000001439	-22.9013	30.02784
f7c15ace-847b-4ba0-9c7d-06fe597c674e	MLM-INFRA-0000001434	-22.9013	29.92916
43779a4c-320c-4463-96ac-586ca345a7cb	MLM-INFRA-0000001433	-22.9013	30.02778
09cdf087-677e-4a85-a5d5-018acc1749a2	MLM-INFRA-0000001377	-22.9005	30.02774
7f7513f3-3ca8-430b-b792-70553ff0e8e6	MLM-INFRA-0000001351	-22.8999	30.02822
88cb8aeb-0ee2-4181-b091-d1f612dd4d76	MLM-INFRA-0000001341	-22.8999	30.02822
2c36f81c-1e4e-456a-a16c-425ade279e10	MLM-INFRA-0000001315	-22.8978	30.03178
b5900a5b-1477-4b85-a8ea-cf4fe5e26ee1	MLM-INFRA-0000001302	-22.8995	30.03714
5a4fdda0-cd98-4716-b5f1-018557628f37	MLM-INFRA-0000001082	-22.8974	30.0344
b6394901-f658-42bb-95ee-378ec2e85264	MLM-INFRA-0000001071	-22.8972	30.03161
3090a2a5-8fc5-4687-8b27-e695c92aaece	MLM-INFRA-0000000978	-22.8952	30.0346
025700ba-c694-4657-8f28-c55c942c8b87	MLM-INFRA-0000000438	-22.7565	30.00184
539a5d94-6105-46a8-b1a0-ef7f58e5885e	MLM-INFRA-0000000310	-22.7079	30.1788
b8f3f935-406f-47f6-a3df-b7c788104c89	MLM-INFRA-0000000199	-22.6333	30.13841
17c36cf8-c3ef-4eda-a3ff-8ec16f4cfd24	MLM-INFRA-0000000195	-22.6312	30.14041
5da63203-7c46-4410-958d-c258f1f41876	MLM-INFRA-0000000185	-22.6261	30.12734

5d7868be-b8fd-42ca-a9b2-eec845f00a48	MLM-INFRA-0000000179	-22.6235	30.13603
911c83df-0616-4cd5-bcf2-716943703a6d	MLM-INFRA-0000000177	-22.6227	30.14029
1265d40b-f07a-4e60-987b-da31d22137f3	MLM-INFRA-0000000176	-22.6226	30.13836
f2ffc411-39f5-4323-8c33-4b355e7e4bd7	MLM-INFRA-0000000173	-22.6207	30.13734
4c07fde3-c7aa-4ed5-977c-418d9783955a	MLM-INFRA-0000000138	-22.6038	30.17793
6d1bd71a-d366-4e76-8ed4-f0315213e84a	MLM-INFRA-0000000050	-22.5173	30.21815
29079c91-921c-4438-97d2-9005cbe6d832	MLM-INFRA-0000000046	-22.515	30.22337
3ad39018-7c39-4b59-ab49-7c7a7d75b620	MLM-INFRA-0000000045	-22.515	30.22337
33d79fe3-5633-45c1-abab-252eceb7ca63	MLM-INFRA-0000000040	-22.5118	30.21766
MLM-INFRA-2023003030	MLM-INFRA-2023003030	-22.9774	30.09939

geometry	DESCRIPTION	CONDITION_CONFIDENCE_GRADING	CRITICALITY_GRADING	UTILIZATION_GRADING	PERFORMANCE_GRADE
POINT (29.	STREET LIGHT	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	STREET LIGHT	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	STREET LIGHT	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	STREET LIGHT	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (30.	SPEED HUMP	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (30.	STOP SIGN	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (30.	SPEED HUMP	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (30.	SPEED HUMP	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (30.	SPEED HUMP	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	STOP SIGN	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	STOP SIGN	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (30.	POLE TRANSFORMER	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	CHEVRON SIGN	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	SPEED HUMP	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	SPEED HUMP	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	CHILDREN CROSSING SIGN	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	SPEED HUMP	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	SPEED HUMP	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	CHEVRON SIGN	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	CHEVRON SIGN	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	CHEVRON SIGN	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	CHEVRON SIGN	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	ASPHALT SURFACE	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (30.	CHEVRON SIGN	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (30.	STREET NAME SIGN	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (30.	CHEVRON SIGN	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	KERB INLET	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (30.	CHEVRON SIGN	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (30.	CHEVRON SIGN	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	KERB INLET	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	KERB INLET	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	KERB INLET	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	KERB INLET	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (30.	BREAKER	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (30.	KERB INLET	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (30.	ASPHALT LAYER	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (30.	STOP SIGN	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (30.	CHEVRON SIGN	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (30.	CHEVRON SIGN	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (30.	CHEVRON SIGN	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE

POINT (29.	1.8M HIGH WIRE MESH	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (30.	2.2M HIGH WIRE MESH	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	FENCE	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	FENCE	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (30.	1.8M HIGH WIRE MESH	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (30.	WENDY HOUSE OFFICE	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (30.	1.8MHIGH WIRE MESH	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	FENCE WIRE MESH	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	RING MAIN UNIT	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	RING MAIN UNIT	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (30.	ASPHALT SURFACE	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
	PAVED (BRICKS)				
POINT (29.	SURFACE	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	KERB INLET	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	KERB INLET	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	STOP SIGN	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	PAVED (BRICKS) LAYER	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (30.	PAVED (BRICKS) LAYER	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	STOP SIGN	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	KERB INLET	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	KERB INLET	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
	PAVED (BRICKS)				
POINT (30.	SURFACE	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	LOW LEVEL CONCRETE	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	ASPHALT SURFACE	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	ASPHALT LAYER	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	KERBING	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
	MUNICIPAL PAVED				
POINT (29.	LAYER	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
	MUNICIPAL PAVED				
POINT (29.	SURFACE	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	KERBING	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	KERBING	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	OTHER	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	OTHER	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	STOP SIGN	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	KERBING	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	ASPHALT SURFACE	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
	MUNICIPAL PAVED				
POINT (29.	SURFACE	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	KERBING	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
	MUNICIPAL PAVED				
POINT (29.	LAYER	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	ASPHALT LAYER	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	KERBING	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	ASPHALT MEDIUM	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	ASPHALT LAYER	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	KERBING	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	ASPHALT SURFACE	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (29.	KERBING	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE

POINT (30.	OVERHEAD LINES	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (30.	POLE TRANSFORMER	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (30.	OVERHEAD LINES	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (30.	POLE TRANSFORMER	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (30.	POLE TRANSFORMER	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (30.	OVERHEAD LINES	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (30.	POLE TRANSFORMER	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (30.	POLE TRANSFORMER	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
	GROUND TRANSFORMER				
POINT (30.	3 PH	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE
POINT (30.	NO OVERTAKE SIGN	ACCURATE	IMPORTANT	NOT USED	SUBSTANTIAL NON-COMPLIANCE

Current Period Reporting Date	UL EXPIRING BEFORE NEXT REPORTING PERIOD (Y/N)	REVIEW COMMENT	REVIEW ASSET (YES/NO)	NBV (2022-2023) Disposed
2023/06/30	FALSE	Do not rev	NO	R 104.94
2023/06/30	FALSE	Do not rev	NO	R 750.68
2023/06/30	FALSE	Do not rev	NO	R 750.68
2023/06/30	FALSE	Do not rev	NO	R 700.64
2023/06/30	FALSE	Do not rev	NO	R 9 618.76
2023/06/30	FALSE	Do not rev	NO	R 483.49
2023/06/30	FALSE	Do not rev	NO	R 9 618.76
2023/06/30	FALSE	Do not rev	NO	R 9 618.76
2023/06/30	FALSE	Do not rev	NO	R 9 618.76
2023/06/30	FALSE	Do not rev	NO	R 6 225.10
2023/06/30	FALSE	Do not rev	NO	R 6 290.02
2023/06/30	FALSE	Do not rev	NO	R 4 236.85
2023/06/30	FALSE	Do not rev	NO	R 1 856.47
2023/06/30	FALSE	Do not rev	NO	R 391 248.56
2023/06/30	FALSE	Do not rev	NO	R 391 248.56
2023/06/30	FALSE	Do not rev	NO	R 1 856.47
2023/06/30	FALSE	Do not rev	NO	R 111 785.30
2023/06/30	FALSE	Do not rev	NO	R 391 248.56
2023/06/30	FALSE	Do not rev	NO	R 1 856.47
2023/06/30	FALSE	Do not rev	NO	R 1 856.47
2023/06/30	FALSE	Do not rev	NO	R 928.23
2023/06/30	FALSE	Do not rev	NO	R 928.23
2023/06/30	FALSE	Do not rev	NO	R 1 974 487.19
2023/06/30	FALSE	Do not rev	NO	R 293.43
2023/06/30	FALSE	Do not rev	NO	R 483.11
2023/06/30	FALSE	Do not rev	NO	R 4 457.17
2023/06/30	FALSE	Do not rev	NO	R 400.53
2023/06/30	FALSE	Do not rev	NO	R 325.72
2023/06/30	FALSE	Do not rev	NO	R 325.72
2023/06/30	FALSE	Do not rev	NO	R 100.13
2023/06/30	FALSE	Do not rev	NO	R 280.37
2023/06/30	FALSE	Do not rev	NO	R 1 081.43
2023/06/30	FALSE	Do not rev	NO	R 200.26
2023/06/30	FALSE	Do not rev	NO	R 155.13
2023/06/30	FALSE	Do not rev	NO	R 3 266.86
2023/06/30	FALSE	Do not rev	NO	R 51 641.84
2023/06/30	FALSE	Do not rev	NO	R 625.18
2023/06/30	FALSE	Do not rev	NO	R 625.18
2023/06/30	FALSE	Do not rev	NO	R 484.74
2023/06/30	FALSE	Do not rev	NO	R 484.74

2023/06/30	FALSE	Do not rev	NO	R	484.74
2023/06/30	FALSE	Do not rev	NO	R	484.74
2023/06/30	FALSE	Do not rev	NO	R	484.74
2023/06/30	FALSE	Do not rev	NO	R	15 868.18
2023/06/30	FALSE	Do not rev	NO	R	818.34
2023/06/30	FALSE	Do not rev	NO	R	966.22
2023/06/30	FALSE	Do not rev	NO	R	495.12
2023/06/30	FALSE	Do not rev	NO	R	24.87
2023/06/30	FALSE	Review UL	NO	R	176 666.87
2023/06/30	FALSE	Do not rev	NO	R	801.06
2023/06/30	FALSE	Do not rev	NO	R	801.06
2023/06/30	FALSE	Do not rev	NO	R	801.06
2023/06/30	FALSE	Do not rev	NO	R	373.83
2023/06/30	FALSE	Do not rev	NO	R	534.04
2023/06/30	FALSE	Review UL	NO	R	150.16
2023/06/30	FALSE	Review UL	NO	R	420.46
2023/06/30	FALSE	Review UL	NO	R	420.46
2023/06/30	FALSE	Review UL	NO	R	600.66
2023/06/30	FALSE	Review UL	NO	R	600.66
2023/06/30	FALSE	Do not rev	NO	R	495.12
2023/06/30	FALSE	Review UL	NO	R	600.66
2023/06/30	FALSE	Do not rev	NO	R	400.53
2023/06/30	FALSE	Do not rev	NO	R	500.46
2023/06/30	FALSE	Do not rev	NO	R	5 919.41
2023/06/30	FALSE	Do not rev	NO	R	944.09
2023/06/30	YES	Review UL	NO	R	-
2023/06/30	FALSE	Do not rev	NO	R	2 329.48
2023/06/30	YES	Review UL	NO	R	-
2023/06/30	FALSE	Do not rev	NO	R	4 067.61
2023/06/30	FALSE	Do not rev	NO	R	6 038.02
2023/06/30	FALSE	Do not rev	NO	R	6 038.02
2023/06/30	FALSE	Do not rev	NO	R	2 302.57
2023/06/30	FALSE	Do not rev	NO	R	4 605.15
2023/06/30	FALSE	Do not rev	NO	R	4 605.15
2023/06/30	FALSE	Do not rev	NO	R	2 302.57
2023/06/30	FALSE	Do not rev	NO	R	2 302.57
2023/06/30	FALSE	Do not rev	NO	R	4 605.15
2023/06/30	FALSE	Do not rev	NO	R	1 279.21
2023/06/30	FALSE	Do not rev	NO	R	4 605.15
2023/06/30	FALSE	Do not rev	NO	R	4 605.15
2023/06/30	FALSE	Do not rev	NO	R	4 605.15
2023/06/30	FALSE	Do not rev	NO	R	1 407.13
2023/06/30	FALSE	Do not rev	NO	R	4 605.15
2023/06/30	FALSE	Do not rev	NO	R	2 302.57
2023/06/30	FALSE	Do not rev	NO	R	2 302.57
2023/06/30	FALSE	Do not rev	NO	R	4 605.15
2023/06/30	FALSE	Do not rev	NO	R	4 605.15
2023/06/30	FALSE	Do not rev	NO	R	2 299.25

2023/06/30	FALSE	Do not rev	NO	R	2 299.25
2023/06/30	FALSE	Do not rev	NO	R	2 299.25
2023/06/30	FALSE	Do not rev	NO	R	2 299.25
2023/06/30	FALSE	Do not rev	NO	R	2 299.25
2023/06/30	FALSE	Do not rev	NO	R	2 299.25
2023/06/30	FALSE	Do not rev	NO	R	1 818.76
2023/06/30	FALSE	Do not rev	NO	R	1 558.93
2023/06/30	FALSE	Do not rev	NO	R	1 558.93
2023/06/30	FALSE	Do not rev	NO	R	1 091.25
2023/06/30	FALSE	Do not rev	NO	R	6 073.63
2023/06/30	FALSE	Do not rev	NO	R	3 374.24
2023/06/30	FALSE	Do not rev	NO	R	6 831.79
2023/06/30	FALSE	Do not rev	NO	R	6 073.63
2023/06/30	FALSE	Do not rev	NO	R	6 073.63
2023/06/30	FALSE	Do not rev	NO	R	6 073.63
2023/06/30	FALSE	Do not rev	NO	R	6 073.63
2023/06/30	FALSE	Do not rev	NO	R	6 073.63
2023/06/30	FALSE	Do not rev	NO	R	4 782.26
2023/06/30	FALSE	Do not rev	NO	R	6 073.63
2023/06/30	FALSE	Do not rev	NO	R	6 073.63
2023/06/30	FALSE	Do not rev	NO	R	6 073.63
2023/06/30	FALSE	Do not rev	NO	R	6 073.63
2023/06/30	FALSE	Do not rev	NO	R	3 036.81
2023/06/30	FALSE	Do not rev	NO	R	6 073.63
2023/06/30	FALSE	Do not rev	NO	R	3 452.99
2023/06/30	FALSE	Do not rev	NO	R	6 905.98
2023/06/30	FALSE	Do not rev	NO	R	6 905.98
2023/06/30	FALSE	Do not rev	NO	R	6 905.98
2023/06/30	FALSE	Do not rev	NO	R	6 905.98
2023/06/30	FALSE	Do not rev	NO	R	6 905.98
2023/06/30	FALSE	Do not rev	NO	R	3 452.99
2023/06/30	FALSE	Do not rev	NO	R	3 452.99
2023/06/30	FALSE	Do not rev	NO	R	4 195.98
2023/06/30	FALSE	Do not rev	NO	R	4 808.59
2023/06/30	FALSE	Do not rev	NO	R	3 776.35
2023/06/30	FALSE	Do not rev	NO	R	9 625.97
2023/06/30	FALSE	Do not rev	NO	R	9 625.97
2023/06/30	FALSE	Do not rev	NO	R	1 925.44
2023/06/30	FALSE	Do not rev	NO	R	894.02
2023/06/30	FALSE	Do not rev	NO	R	16 359.19
2023/06/30	FALSE	Do not rev	NO	R	7 341.35
2023/06/30	FALSE	Do not rev	NO	R	63 118.30
2023/06/30	FALSE	Do not rev	NO	R	16 761.09
2023/06/30	FALSE	Do not rev	NO	R	2 568.06

2023/06/30	FALSE	Do not rev	NO	R	1 387.24
2023/06/30	FALSE	Do not rev	NO	R	98 530.97
2023/06/30	FALSE	Do not rev	NO	R	10 694.73
2023/06/30	FALSE	Do not rev	NO	R	6 074.78
2023/06/30	FALSE	Do not rev	NO	R	3 881.24
2023/06/30	FALSE	Do not rev	NO	R	1 805.07
2023/06/30	FALSE	Do not rev	NO	R	487.58
2023/06/30	FALSE	Do not rev	NO	R	94 602.65
2023/06/30	YES	Review UL	NO	R	140 000.00
2023/06/30	YES	Review UL	NO	R	140 000.00
2023/06/30	FALSE	Review UL	NO	R	28 000.15
2023/06/30	FALSE	Review UL	NO	R	16 873.17
2023/06/30	FALSE	Do not rev	NO	R	179 664.02
2023/06/30	FALSE	Do not rev	NO	R	44 916.00
2023/06/30	FALSE	Review UL	NO	R	8 854.95
2023/06/30	FALSE	Review UL	NO	R	55 077.94
2023/06/30	FALSE	Review UL	NO	R	68 345.69
2023/06/30	FALSE	Review UL	NO	R	8 854.95
2023/06/30	FALSE	Do not rev	NO	R	89 832.01
2023/06/30	FALSE	Do not rev	NO	R	179 664.02
2023/06/30	FALSE	Review UL	NO	R	5 234.44
2023/06/30	FALSE	Do not rev	NO	R	8 707.94
2023/06/30	FALSE	Review UL	NO	R	10 298.45
2023/06/30	FALSE	Review UL	NO	R	24 436.37
2023/06/30	FALSE	Do not rev	NO	R	70 651.06
2023/06/30	FALSE	Do not rev	NO	R	489.08
2023/06/30	FALSE	Review UL	NO	R	39.12
2023/06/30	FALSE	Do not rev	NO	R	345.66
2023/06/30	FALSE	Do not rev	NO	R	241.96
2023/06/30	FALSE	Do not rev	NO	R	157.40
2023/06/30	FALSE	Review UL	NO	R	1 215.08
2023/06/30	FALSE	Do not rev	NO	R	125.97
2023/06/30	FALSE	Do not rev	NO	R	389.97
2023/06/30	FALSE	Review UL	NO	R	10 675.52
2023/06/30	FALSE	Review UL	NO	R	44.14
2023/06/30	FALSE	Do not rev	NO	R	389.97
2023/06/30	FALSE	Do not rev	NO	R	551.79
2023/06/30	FALSE	Review UL	NO	R	25 331.11
2023/06/30	FALSE	Do not rev	NO	R	73 237.96
2023/06/30	FALSE	Do not rev	NO	R	42.66
2023/06/30	FALSE	Review UL	NO	R	24 438.47
2023/06/30	FALSE	Do not rev	NO	R	70 657.14
2023/06/30	FALSE	Review UL	NO	R	10 299.33
2023/06/30	FALSE	Do not rev	NO	R	363.38

2023/06/30	FALSE	Review UL	NO	R	41.13
2023/06/30	FALSE	Do not rev	NO	R	363.38
2023/06/30	FALSE	Do not rev	NO	R	514.17
2023/06/30	FALSE	Review UL	NO	R	33.10
2023/06/30	FALSE	Do not rev	NO	R	413.84
2023/06/30	FALSE	Review UL	NO	R	8 344.23
2023/06/30	FALSE	Do not rev	NO	R	292.48
2023/06/30	FALSE	Do not rev	NO	R	292.48
2023/06/30	FALSE	Do not rev	NO	R	57 244.43
2023/06/30	FALSE	Review UL	NO	R	19 799.36
2023/06/30	FALSE	Review UL	NO	R	12 983.63
2023/06/30	FALSE	Review UL	NO	R	73.23
2023/06/30	FALSE	Do not rev	NO	R	915.46
2023/06/30	FALSE	Review UL	NO	R	30 807.83
2023/06/30	FALSE	Do not rev	NO	R	127 246.28
2023/06/30	FALSE	Do not rev	NO	R	647.00
2023/06/30	FALSE	Do not rev	NO	R	647.00
2023/06/30	FALSE	Do not rev	NO	R	1 368.04
2023/06/30	FALSE	Do not rev	NO	R	576.55
2023/06/30	FALSE	Do not rev	NO	R	3 071.95
2023/06/30	FALSE	Do not rev	NO	R	1 063.56
2023/06/30	FALSE	Do not rev	NO	R	1 063.56
2023/06/30	FALSE	Review UL	NO	R	21 127.12
2023/06/30	FALSE	Review UL	NO	R	50 130.86
2023/06/30	FALSE	Do not rev	NO	R	207 056.64
2023/06/30	FALSE	Review UL	NO	R	120.37
2023/06/30	FALSE	Do not rev	NO	R	1 504.87
2023/06/30	FALSE	Do not rev	NO	R	125.97
2023/06/30	FALSE	Do not rev	NO	R	761.38
2023/06/30	FALSE	Do not rev	NO	R	273.23
2023/06/30	FALSE	Do not rev	NO	R	18 980.97
2023/06/30	FALSE	Do not rev	NO	R	876.48
2023/06/30	FALSE	Do not rev	NO	R	115.15
2023/06/30	FALSE	Do not rev	NO	R	332 103.24
2023/06/30	FALSE	Review UL	NO	R	57 432.94
2023/06/30	FALSE	Do not rev	NO	R	1 689.85
2023/06/30	FALSE	Do not rev	NO	R	1 706.12
2023/06/30	FALSE	Do not rev	NO	R	1 706.12
2023/06/30	FALSE	Review UL	NO	R	135.17
2023/06/30	FALSE	Do not rev	NO	R	1 522.75

2023/06/30	FALSE	Do not rev	NO	R	125.97
2023/06/30	FALSE	Review UL	NO	R	2 244.58
2023/06/30	FALSE	Review UL	NO	R	5 325.99
2023/06/30	FALSE	Do not rev	NO	R	61 594.56
2023/06/30	FALSE	Do not rev	NO	R	225.73
2023/06/30	FALSE	Review UL	NO	R	18.06
2023/06/30	FALSE	Do not rev	NO	R	319.07
2023/06/30	FALSE	Do not rev	NO	R	319.07
2023/06/30	FALSE	Review UL	NO	R	45.99
2023/06/30	FALSE	Do not rev	NO	R	125.97
2023/06/30	FALSE	Do not rev	NO	R	3 045.50
2023/06/30	FALSE	Review UL	NO	R	5 855.95
2023/06/30	FALSE	Review UL	NO	R	13 895.11
2023/06/30	FALSE	Do not rev	NO	R	580.52
2023/06/30	FALSE	Do not rev	NO	R	580.52
2023/06/30	FALSE	Do not rev	NO	R	574.99
2023/06/30	FALSE	Do not rev	NO	R	114 782.62
2023/06/30	FALSE	Do not rev	NO	R	345.66
2023/06/30	FALSE	Do not rev	NO	R	3 045.50
2023/06/30	FALSE	Do not rev	NO	R	345.66
2023/06/30	FALSE	Do not rev	NO	R	33 008.81
2023/06/30	FALSE	Do not rev	NO	R	244.54
2023/06/30	FALSE	Review UL	NO	R	11 363.88
2023/06/30	FALSE	Do not rev	NO	R	67 052.14
2023/06/30	FALSE	Review UL	NO	R	19.56
2023/06/30	FALSE	Review UL	NO	R	4 789.19
2023/06/30	FALSE	Review UL	NO	R	20 656.74
2023/06/30	FALSE	Review UL	NO	R	8 705.56
2023/06/30	FALSE	Do not rev	NO	R	390.06
2023/06/30	FALSE	Review UL	NO	R	21.57
2023/06/30	FALSE	Do not rev	NO	R	266.78
2023/06/30	FALSE	Do not rev	NO	R	381.11
2023/06/30	FALSE	Do not rev	NO	R	74 654.12
2023/06/30	FALSE	Review UL	NO	R	2 033.41
2023/06/30	FALSE	Do not rev	NO	R	345.66
2023/06/30	FALSE	Do not rev	NO	R	489.08
2023/06/30	FALSE	Review UL	NO	R	39.12
2023/06/30	FALSE	Do not rev	NO	R	345.66
2023/06/30	FALSE	Do not rev	NO	R	67 071.15
2023/06/30	FALSE	Review UL	NO	R	6 843.63

2023/06/30	FALSE	Do not rev	NO	R	10 168.22
2023/06/30	FALSE	Do not rev	NO	R	1 003.25
2023/06/30	FALSE	Do not rev	NO	R	709.04
2023/06/30	FALSE	Do not rev	NO	R	709.04
2023/06/30	FALSE	Do not rev	NO	R	24 127.36
2023/06/30	FALSE	Do not rev	NO	R	77 397.21
2023/06/30	FALSE	Review UL	NO	R	80.25
2023/06/30	FALSE	Do not rev	NO	R	6 969.21
2023/06/30	FALSE	Do not rev	NO	R	50.39
2023/06/30	FALSE	Do not rev	NO	R	8 444.57
2023/06/30	FALSE	Do not rev	NO	R	1 779.44
2023/06/30	FALSE	Do not rev	NO	R	157.40
2023/06/30	FALSE	Do not rev	NO	R	157.40
2023/06/30	FALSE	Do not rev	NO	R	157.40
2023/06/30	FALSE	Do not rev	NO	R	157.40
2023/06/30	FALSE	Do not rev	NO	R	125.97
2023/06/30	FALSE	Do not rev	NO	R	8 493.93
2023/06/30	FALSE	Do not rev	NO	R	19 073.15
2023/06/30	FALSE	Do not rev	NO	R	3 579.68
2023/06/30	FALSE	Do not rev	NO	-R	0.00
2023/06/30	FALSE	Do not rev	NO	R	29 238.22
2023/06/30	FALSE	Do not rev	NO	R	6 510.40
2023/06/30	FALSE	Do not rev	NO	R	8 198.90
2023/06/30	FALSE	Do not rev	NO	R	36 821.31
2023/06/30	FALSE	Do not rev	NO	R	4 837.48
2023/06/30	FALSE	Do not rev	NO	R	10 095.30
2023/06/30	FALSE	Do not rev	NO	R	32 384.32
2023/06/30	FALSE	Do not rev	NO	R	4 254.56
2023/06/30	FALSE	Do not rev	NO	R	5 513.21
2023/06/30	FALSE	Do not rev	NO	R	21 307.13
2023/06/30	FALSE	Do not rev	NO	R	6 642.16
2023/06/30	FALSE	Do not rev	NO	R	157.40
2023/06/30	FALSE	Do not rev	NO	R	2 799.27
2023/06/30	FALSE	Do not rev	NO	R	6 095.56
2023/06/30	FALSE	Do not rev	NO	R	3 319.26
2023/06/30	FALSE	Do not rev	NO	R	4 166.18
2023/06/30	FALSE	Do not rev	NO	R	14 122.30
2023/06/30	FALSE	Do not rev	NO	R	17 685.60
2023/06/30	FALSE	Do not rev	NO	R	23 101.11
2023/06/30	FALSE	Do not rev	NO	R	157.40
2023/06/30	FALSE	Do not rev	NO	R	61 308.87
2023/06/30	FALSE	Do not rev	NO	R	27 302.96
2023/06/30	FALSE	Do not rev	NO	R	11 506.54
2023/06/30	FALSE	Do not rev	NO	R	1 508.67
2023/06/30	FALSE	Do not rev	NO	R	16 076.95
2023/06/30	FALSE	Do not rev	NO	R	23 846.50
2023/06/30	FALSE	Do not rev	NO	R	1 177.20
2023/06/30	FALSE	Do not rev	NO	R	2 179.52

2023/06/30	FALSE	Do not rev	NO	R	1 575.47
2023/06/30	FALSE	Do not rev	NO	R	2 793.28
2023/06/30	FALSE	Do not rev	NO	R	5 092.18
2023/06/30	FALSE	Do not rev	NO	R	12 082.83
2023/06/30	FALSE	Do not rev	NO	R	27 132.02
2023/06/30	FALSE	Do not rev	NO	R	5 171.60
2023/06/30	FALSE	Do not rev	NO	R	23 225.70
2023/06/30	FALSE	Do not rev	NO	R	1 118.89
2023/06/30	FALSE	Do not rev	NO	R	2 654.92
2023/06/30	FALSE	Do not rev	NO	R	1 789.91
2023/06/30	FALSE	Do not rev	NO	R	2 670.23
2023/06/30	FALSE	Do not rev	NO	R	23 984.02
2023/06/30	FALSE	Do not rev	NO	R	1 083.91
2023/06/30	FALSE	Do not rev	NO	R	25 089.27
2023/06/30	FALSE	Do not rev	NO	R	2 571.93
2023/06/30	FALSE	Do not rev	NO	R	53.30
2023/06/30	FALSE	Do not rev	NO	R	54 948.54
2023/06/30	FALSE	Do not rev	NO	R	27 474.27
2023/06/30	FALSE	Do not rev	NO	R	867.18
2023/06/30	FALSE	Do not rev	NO	R	232.37
2023/06/30	FALSE	Do not rev	NO	R	35 696.50
2023/06/30	FALSE	Do not rev	NO	R	54 948.54
2023/06/30	FALSE	Do not rev	NO	R	35 696.50
2023/06/30	FALSE	Do not rev	NO	R	54 948.54
2023/06/30	FALSE	Do not rev	NO	R	1 215.39
2023/06/30	FALSE	Do not rev	NO	R	54 948.54
2023/06/30	FALSE	Do not rev	NO	R	27 474.27
2023/06/30	FALSE	Do not rev	NO	R	74 000.04
2023/06/30	FALSE	Do not rev	NO	R	54 948.54
2023/06/30	FALSE	Do not rev	NO	R	54 948.54
2023/06/30	FALSE	Do not rev	NO	R	54 948.54
2023/06/30	FALSE	Do not rev	NO	R	2 989.74
2023/06/30	FALSE	Do not rev	NO	R	74 000.04
2023/06/30	FALSE	Do not rev	NO	R	54 948.54
2023/06/30	FALSE	Do not rev	NO	R	4 686.58
2023/06/30	FALSE	Do not rev	NO	R	35 696.50
2023/06/30	FALSE	Do not rev	NO	R	35 696.50
2023/06/30	FALSE	Do not rev	NO	R	589.54
2023/06/30	FALSE	Do not rev	NO	R	6 467.79
2023/06/30	FALSE	Do not rev	NO	R	30 340.85
2023/06/30	FALSE	Do not rev	NO	R	74 000.04
2023/06/30	FALSE	Do not rev	NO	R	26 633.18
2023/06/30	FALSE	Do not rev	NO	R	22 075.91
2023/06/30	FALSE	Do not rev	NO	R	35 696.50
2023/06/30	FALSE	Do not rev	NO	R	54 948.54
2023/06/30	FALSE	Do not rev	NO	R	54 948.54
2023/06/30	FALSE	Do not rev	NO	R	35 696.50
2023/06/30	FALSE	Do not rev	NO	R	54 948.54

2023/06/30	FALSE	Do not rev	NO	R	27 474.27
2023/06/30	FALSE	Do not rev	NO	R	35 696.50
2023/06/30	FALSE	Do not rev	NO	R	43 165.39
2023/06/30	FALSE	Do not rev	NO	R	45 930.14
2023/06/30	FALSE	Do not rev	NO	R	19 356.77
2023/06/30	FALSE	Do not rev	NO	R	35 696.50
2023/06/30	FALSE	Do not rev	NO	R	19 299.68
2023/06/30	FALSE	Do not rev	NO	R	8 133.64
2023/06/30	FALSE	Do not rev	NO	R	30 461.30
2023/06/30	FALSE	Do not rev	NO	R	12 837.59
2023/06/30	FALSE	Do not rev	NO	R	4 522.29
2023/06/30	FALSE	Do not rev	NO	R	10 730.58
2023/06/30	FALSE	Review UL	NO	R	96 944.49
2023/06/30	FALSE	Review UL	NO	R	40 856.22
2023/06/30	FALSE	Do not rev	NO	R	8 707.94
2023/06/30	FALSE	Do not rev	NO	R	1 869.59
2023/06/30	FALSE	Do not rev	NO	R	49 358.71
2023/06/30	FALSE	Do not rev	NO	R	20 801.70
2023/06/30	FALSE	Do not rev	NO	R	35 696.50
2023/06/30	FALSE	Do not rev	NO	R	12 947.48
2023/06/30	FALSE	Do not rev	NO	R	30 722.05
2023/06/30	FALSE	Do not rev	NO	R	34 468.28
2023/06/30	FALSE	Do not rev	NO	R	81 787.05
2023/06/30	FALSE	Do not rev	NO	R	20 801.11
2023/06/30	FALSE	Do not rev	NO	R	49 357.29
2023/06/30	FALSE	Do not rev	NO	R	110.18
2023/06/30	FALSE	Do not rev	NO	R	54 948.54
2023/06/30	FALSE	Do not rev	NO	R	14 686.74
2023/06/30	FALSE	Do not rev	NO	R	69 697.98
2023/06/30	FALSE	Do not rev	NO	R	54 948.54
2023/06/30	FALSE	Do not rev	NO	R	102 743.55
2023/06/30	FALSE	Do not rev	NO	R	4 371.08
2023/06/30	FALSE	Do not rev	NO	R	67 963.57
2023/06/30	FALSE	Do not rev	NO	R	28 642.52
2023/06/30	FALSE	Do not rev	NO	R	6 281.34
2023/06/30	FALSE	Do not rev	NO	R	21 292.14
2023/06/30	FALSE	Do not rev	NO	R	54 948.54
2023/06/30	FALSE	Do not rev	NO	R	65 299.09
2023/06/30	FALSE	Do not rev	NO	R	27 519.61
2023/06/30	FALSE	Do not rev	NO	R	35 696.50
2023/06/30	FALSE	Do not rev	NO	R	925.30
2023/06/30	FALSE	Do not rev	NO	R	52 780.65
2023/06/30	FALSE	Do not rev	NO	R	22 243.84
2023/06/30	FALSE	Do not rev	NO	R	27 474.27
2023/06/30	FALSE	Do not rev	NO	R	114 108.46
2023/06/30	FALSE	Do not rev	NO	R	742.78
2023/06/30	FALSE	Do not rev	NO	R	5 704.87
2023/06/30	FALSE	Do not rev	NO	R	13 536.64
2023/06/30	FALSE	Review UL	NO	R	205 686.81

2023/06/30	FALSE	Review UL	NO	R 222 315.43
2023/06/30	FALSE	Review UL	NO	R 86 684.51
2023/06/30	FALSE	Do not rev	NO	R 9 947.24
2023/06/30	FALSE	Do not rev	NO	R 62.99
2023/06/30	FALSE	Do not rev	NO	R 88.18
2023/06/30	FALSE	Do not rev	NO	R 125.97
2023/06/30	FALSE	Do not rev	NO	R 101 946.94
2023/06/30	FALSE	Do not rev	NO	R 31 780.35
2023/06/30	FALSE	Do not rev	NO	R 19 133.55
2023/06/30	FALSE	Review UL	NO	R 1 728.26
2023/06/30	FALSE	Do not rev	NO	R 1 920.84
2023/06/30	FALSE	Do not rev	NO	R 10 849.30
2023/06/30	FALSE	Review UL	NO	R 1 728.26
2023/06/30	FALSE	Do not rev	NO	R 157.40
2023/06/30	FALSE	Do not rev	NO	R 35.27
2023/06/30	FALSE	Do not rev	NO	R 19 132.15
2023/06/30	FALSE	Do not rev	NO	R 45 397.15
2023/06/30	FALSE	Do not rev	NO	R 101 939.44
2023/06/30	FALSE	Do not rev	NO	R 157.40
2023/06/30	FALSE	Do not rev	NO	R 870.14
2023/06/30	FALSE	Do not rev	NO	R 125.97
2023/06/30	FALSE	Do not rev	NO	R 761.38
2023/06/30	FALSE	Do not rev	NO	R 27 039.62
2023/06/30	FALSE	Do not rev	NO	R 170 009.14
2023/06/30	FALSE	Do not rev	NO	R 11 395.56
2023/06/30	FALSE	Do not rev	NO	R 125.97
2023/06/30	FALSE	Do not rev	NO	R 125.97
2023/06/30	FALSE	Do not rev	NO	R 1 184.73
2023/06/30	FALSE	Do not rev	NO	R 125.97
2023/06/30	FALSE	Do not rev	NO	R 33.09
2023/06/30	FALSE	Do not rev	NO	R 1 087.68
2023/06/30	FALSE	Do not rev	NO	R 1 514.38
2023/06/30	FALSE	Do not rev	NO	R 47 526.77
2023/06/30	FALSE	Do not rev	NO	R 232 016.67
2023/06/30	FALSE	Do not rev	NO	R 105 262.57
2023/06/30	FALSE	Do not rev	NO	R 291 520.70
2023/06/30	FALSE	Review UL	NO	R 29 745.44
2023/06/30	FALSE	Review UL	NO	R 70 580.60
2023/06/30	FALSE	Do not rev	NO	R 2 974.44
2023/06/30	FALSE	Do not rev	NO	R 7 057.81
2023/06/30	FALSE	Do not rev	NO	R 2 175.36
2023/06/30	FALSE	Do not rev	NO	R 14 731.63
2023/06/30	FALSE	Do not rev	NO	R 220.37
2023/06/30	FALSE	Do not rev	NO	R 870.14
2023/06/30	FALSE	Do not rev	NO	R 1 386.33
2023/06/30	FALSE	Do not rev	NO	R 157.40
2023/06/30	FALSE	Do not rev	NO	R 990.24
2023/06/30	FALSE	Do not rev	NO	R 74.62

2023/06/30	FALSE	Do not rev	NO	R	2 175.36
2023/06/30	FALSE	Do not rev	NO	R	50.39
2023/06/30	FALSE	Do not rev	NO	R	2 250.31
2023/06/30	FALSE	Do not rev	NO	R	62.96
2023/06/30	FALSE	Do not rev	NO	R	990.24
2023/06/30	FALSE	Do not rev	NO	R	2 577.19
2023/06/30	FALSE	Do not rev	NO	R	324.25
2023/06/30	FALSE	Do not rev	NO	R	990.24
2023/06/30	FALSE	Do not rev	NO	R	125.97
2023/06/30	FALSE	Do not rev	NO	R	346.58
2023/06/30	FALSE	Do not rev	NO	R	1 060.88
2023/06/30	FALSE	Do not rev	NO	R	1 584.38
2023/06/30	FALSE	Do not rev	NO	R	62.96
2023/06/30	FALSE	Do not rev	NO	R	405.30
2023/06/30	FALSE	Do not rev	NO	R	990.24
2023/06/30	FALSE	Do not rev	NO	R	990.24
2023/06/30	FALSE	Do not rev	NO	R	62.96
2023/06/30	FALSE	Do not rev	NO	R	324.25
2023/06/30	FALSE	Do not rev	NO	R	157.40
2023/06/30	FALSE	Do not rev	NO	R	324.25
2023/06/30	FALSE	Do not rev	NO	R	50.39
2023/06/30	FALSE	Do not rev	NO	R	324.25
2023/06/30	FALSE	Do not rev	NO	R	990.24
2023/06/30	FALSE	Do not rev	NO	R	62.96
2023/06/30	FALSE	Do not rev	NO	R	324.25
2023/06/30	FALSE	Do not rev	NO	R	1 584.38
2023/06/30	FALSE	Do not rev	NO	R	324.25
2023/06/30	FALSE	Do not rev	NO	R	1 386.33
2023/06/30	FALSE	Do not rev	NO	R	16 679.72
2023/06/30	FALSE	Do not rev	NO	R	10 059.17
2023/06/30	FALSE	Do not rev	NO	R	3 772.19
2023/06/30	FALSE	Do not rev	NO	R	405.30
2023/06/30	FALSE	Do not rev	NO	R	251.85
2023/06/30	FALSE	Do not rev	NO	R	324.25
2023/06/30	FALSE	Do not rev	NO	R	324.25
2023/06/30	FALSE	Do not rev	NO	R	990.24
2023/06/30	FALSE	Do not rev	NO	R	11 779.66
2023/06/30	FALSE	Do not rev	NO	R	324.25
2023/06/30	FALSE	Review UL	NO	R	71 895.66
2023/06/30	FALSE	Do not rev	NO	R	176.36
2023/06/30	FALSE	Do not rev	NO	R	202 735.77
2023/06/30	FALSE	Do not rev	NO	R	176.36
2023/06/30	FALSE	Review UL	NO	R	1 484.61
2023/06/30	FALSE	Do not rev	NO	R	62.96
2023/06/30	FALSE	Review UL	NO	R	52 911.72
2023/06/30	FALSE	Do not rev	NO	R	47 712.31
2023/06/30	FALSE	Do not rev	NO	R	157.40

2023/06/30	FALSE	Do not rev	NO	R	324.25
2023/06/30	FALSE	Do not rev	NO	R	125.97
2023/06/30	FALSE	Do not rev	NO	R	324.25
2023/06/30	FALSE	Do not rev	NO	R	62.96
2023/06/30	FALSE	Do not rev	NO	R	2 175.36
2023/06/30	FALSE	Review UL	NO	R	1 104.73
2023/06/30	FALSE	Review UL	NO	R	22 950.53
2023/06/30	FALSE	Do not rev	NO	R	715 257.71
2023/06/30	FALSE	Do not rev	NO	R	318 528.97
2023/06/30	FALSE	Do not rev	NO	R	870.14
2023/06/30	FALSE	Do not rev	NO	R	349 943.97
2023/06/30	FALSE	Review UL	NO	R	28 806.71
2023/06/30	FALSE	Do not rev	NO	R	897 766.54
2023/06/30	FALSE	Do not rev	NO	R	8 707.94
2023/06/30	FALSE	Do not rev	NO	R	2 175.36
2023/06/30	FALSE	Do not rev	NO	R	399 806.46
2023/06/30	FALSE	Do not rev	NO	R	435.07
2023/06/30	FALSE	Review UL	NO	R	15 813.58
2023/06/30	FALSE	Do not rev	NO	R	1 522.75
2023/06/30	FALSE	Review UL	NO	R	51 009.55
2023/06/30	FALSE	Do not rev	NO	R	219 475.74
2023/06/30	FALSE	Do not rev	NO	R	157.40
2023/06/30	FALSE	Do not rev	NO	R	792.51
2023/06/30	FALSE	Do not rev	NO	R	985 666.81
2023/06/30	FALSE	Do not rev	NO	R	74.62
2023/06/30	FALSE	Review UL	NO	R	1 484.61
2023/06/30	FALSE	Do not rev	NO	R	251.85
2023/06/30	FALSE	Do not rev	NO	R	251.85
2023/06/30	FALSE	Review UL	NO	R	1 728.26
2023/06/30	FALSE	Do not rev	NO	R	12 191.12
2023/06/30	FALSE	Review UL	NO	R	85 297.76
2023/06/30	FALSE	Do not rev	NO	R	3 600.49
2023/06/30	FALSE	Do not rev	NO	R	176.36
2023/06/30	FALSE	Do not rev	NO	R	8 707.94
2023/06/30	FALSE	Do not rev	NO	R	220.37
2023/06/30	FALSE	Review UL	NO	R	40 243.10
2023/06/30	FALSE	Do not rev	NO	R	193 257.54
2023/06/30	FALSE	Do not rev	NO	R	52.55
2023/06/30	FALSE	Do not rev	NO	R	125.97
2023/06/30	FALSE	Do not rev	NO	R	2 250.31
2023/06/30	FALSE	Do not rev	NO	R	53.30
2023/06/30	FALSE	Do not rev	NO	R	10 214.07
2023/06/30	FALSE	Do not rev	NO	R	1 826.39
2023/06/30	FALSE	Do not rev	NO	R	400.37
2023/06/30	FALSE	Do not rev	NO	R	157.40
2023/06/30	FALSE	Do not rev	NO	R	157.40
2023/06/30	FALSE	Do not rev	NO	R	2 250.31
2023/06/30	FALSE	Do not rev	NO	R	125.97
2023/06/30	FALSE	Do not rev	NO	R	220.37

2023/06/30	FALSE	Do not rev	NO	R	14 731.63
2023/06/30	FALSE	Do not rev	NO	R	220.37
2023/06/30	FALSE	Do not rev	NO	R	21.32
2023/06/30	FALSE	Review UL	NO	R	826.09
2023/06/30	FALSE	Review UL	NO	R	1 960.17
2023/06/30	FALSE	Do not rev	NO	R	157.40
2023/06/30	FALSE	Do not rev	NO	R	251.85
2023/06/30	FALSE	Do not rev	NO	R	125.97
2023/06/30	FALSE	Do not rev	NO	R	125.97
2023/06/30	FALSE	Review UL	NO	R	10 396.88
2023/06/30	FALSE	Review UL	NO	R	35 242.76
2023/06/30	FALSE	Do not rev	NO	R	125.97
2023/06/30	FALSE	Do not rev	NO	R	71 326.36
2023/06/30	FALSE	Review UL	NO	R	18 517.29
2023/06/30	FALSE	Review UL	NO	R	7 803.91
2023/06/30	FALSE	Do not rev	NO	R	8 533.78
2023/06/30	FALSE	Review UL	NO	R	551 677.83
2023/06/30	FALSE	Do not rev	NO	R	3 784 709.22
2023/06/30	FALSE	Do not rev	NO	R	53 537.67
2023/06/30	FALSE	Do not rev	NO	R	8 707.94
2023/06/30	FALSE	Review UL	NO	R	1 309 032.60
2023/06/30	FALSE	Do not rev	NO	R	125.97
2023/06/30	FALSE	Review UL	NO	R	22 436.76
2023/06/30	FALSE	Do not rev	NO	R	792.51
2023/06/30	FALSE	Review UL	NO	R	9 455.74
2023/06/30	FALSE	Do not rev	NO	R	8 707.94
2023/06/30	FALSE	Do not rev	NO	R	13 390.85
2023/06/30	FALSE	Do not rev	NO	R	125.97
2023/06/30	FALSE	Review UL	NO	R	1 484.61
2023/06/30	FALSE	Do not rev	NO	R	14 969.06
2023/06/30	FALSE	Do not rev	NO	R	21.36
2023/06/30	FALSE	Do not rev	NO	R	125.97
2023/06/30	FALSE	Review UL	NO	R	2 678.50
2023/06/30	FALSE	Do not rev	NO	R	621.45
2023/06/30	FALSE	Do not rev	NO	R	157.40
2023/06/30	FALSE	Do not rev	NO	R	78.70
2023/06/30	FALSE	Do not rev	NO	R	900.12
2023/06/30	FALSE	Do not rev	NO	R	157.40
2023/06/30	FALSE	Do not rev	NO	R	62.96
2023/06/30	FALSE	Do not rev	NO	R	144 046.00
2023/06/30	FALSE	Do not rev	NO	R	144 046.00
2023/06/30	FALSE	Do not rev	NO	R	53.30
2023/06/30	FALSE	Do not rev	NO	R	12 509.31
2023/06/30	FALSE	Do not rev	NO	R	792.51
2023/06/30	FALSE	Do not rev	NO	R	78.70
2023/06/30	FALSE	Do not rev	NO	R	157.40
2023/06/30	FALSE	Do not rev	NO	R	157.40
2023/06/30	FALSE	Do not rev	NO	R	125.97
2023/06/30	FALSE	Do not rev	NO	R	157.40

2023/06/30	FALSE	Do not rev	NO	R	125.97
2023/06/30	FALSE	Do not rev	NO	R	51 982.48
2023/06/30	FALSE	Do not rev	NO	R	16 679.72
2023/06/30	FALSE	Do not rev	NO	R	14 731.63
2023/06/30	FALSE	Do not rev	NO	R	157.40
2023/06/30	FALSE	Do not rev	NO	R	2 250.31
2023/06/30	FALSE	Do not rev	NO	R	53.30
2023/06/30	FALSE	Do not rev	NO	R	297.37
2023/06/30	FALSE	Do not rev	NO	R	22 847.57
2023/06/30	FALSE	Do not rev	NO	R	157.40
2023/06/30	FALSE	Do not rev	NO	R	125.97
2023/06/30	FALSE	Do not rev	NO	R	157.40
2023/06/30	FALSE	Do not rev	NO	R	125.97
2023/06/30	FALSE	Do not rev	NO	R	14 731.63
2023/06/30	FALSE	Do not rev	NO	R	78.70
2023/06/30	FALSE	Do not rev	NO	R	10 059.17
2023/06/30	FALSE	Do not rev	NO	R	2 250.31
2023/06/30	FALSE	Do not rev	NO	R	157.40
2023/06/30	FALSE	Do not rev	NO	R	125.97
2023/06/30	FALSE	Do not rev	NO	R	50.39
2023/06/30	FALSE	Do not rev	NO	R	324.25
2023/06/30	FALSE	Do not rev	NO	R	157.40
2023/06/30	FALSE	Do not rev	NO	R	990.24
2023/06/30	FALSE	Do not rev	NO	R	3 483.18
2023/06/30	FALSE	Do not rev	NO	R	1 584.38
2023/06/30	FALSE	Do not rev	NO	R	125.97
2023/06/30	FALSE	Do not rev	NO	R	21.32
2023/06/30	FALSE	Do not rev	NO	R	176.36
2023/06/30	FALSE	Do not rev	NO	R	2 767.42
2023/06/30	FALSE	Do not rev	NO	R	157.40
2023/06/30	FALSE	Do not rev	NO	R	6 566.60
2023/06/30	FALSE	Do not rev	NO	R	53.30
2023/06/30	FALSE	Do not rev	NO	R	22 495.41
2023/06/30	FALSE	Review UL	NO	R	26 062.78
2023/06/30	FALSE	Review UL	NO	R	10 983.88
2023/06/30	FALSE	Do not rev	NO	R	107 647.72
2023/06/30	FALSE	Review UL	NO	R	3 749.02
2023/06/30	FALSE	Do not rev	NO	R	102 930.06
2023/06/30	FALSE	Review UL	NO	R	36 327.24
2023/06/30	FALSE	Review UL	NO	R	8 895.76
2023/06/30	FALSE	Do not rev	NO	R	51 439.33
2023/06/30	FALSE	Review UL	NO	R	10 716.81
2023/06/30	FALSE	Review UL	NO	R	8 413.13
2023/06/30	FALSE	Do not rev	NO	R	24 247.91
2023/06/30	FALSE	Review UL	NO	R	3 545.62
2023/06/30	FALSE	Review UL	NO	R	2 709.72
2023/06/30	FALSE	Review UL	NO	R	9 185.24
2023/06/30	FALSE	Do not rev	NO	R	26 556.62
2023/06/30	FALSE	Do not rev	NO	R	125.97
2023/06/30	FALSE	Do not rev	NO	R	28 060.33

2023/06/30	FALSE	Do not rev	NO	R 11 825.73
2023/06/30	FALSE	Review UL	NO	R 1 728.26
2023/06/30	FALSE	Do not rev	NO	R 126 019.09
2023/06/30	FALSE	Do not rev	NO	R 157.40
2023/06/30	FALSE	Review UL	NO	R 26 688.35
2023/06/30	FALSE	Do not rev	NO	R 62.96
2023/06/30	FALSE	Do not rev	NO	R 17.64
2023/06/30	FALSE	Do not rev	NO	R 85 492.53
2023/06/30	FALSE	Do not rev	NO	R 176.36
2023/06/30	FALSE	Do not rev	NO	R 16 045.37
2023/06/30	FALSE	Do not rev	NO	R 26 650.94
2023/06/30	FALSE	Do not rev	NO	R 157.40
2023/06/30	FALSE	Review UL	NO	R 63 326.68
2023/06/30	FALSE	Do not rev	NO	R 1 087.68
2023/06/30	FALSE	Do not rev	NO	R 125.97
2023/06/30	FALSE	Do not rev	NO	R 1 450.24
2023/06/30	FALSE	Do not rev	NO	R 6 573.41
2023/06/30	FALSE	Do not rev	NO	R 15 597.53
2023/06/30	FALSE	Do not rev	NO	R 35 024.31
2023/06/30	FALSE	Do not rev	NO	R 125.97
2023/06/30	FALSE	Do not rev	NO	R 1 450.24
2023/06/30	FALSE	Do not rev	NO	R 125.97
2023/06/30	FALSE	Do not rev	NO	R 12 144.45
2023/06/30	FALSE	Do not rev	NO	R 27 014.63
2023/06/30	FALSE	Do not rev	NO	R 27 014.63
2023/06/30	FALSE	Do not rev	NO	R 14 822.58
2023/06/30	FALSE	Do not rev	NO	R 23 298.91
2023/06/30	FALSE	Do not rev	NO	R 6 246.82
2023/06/30	FALSE	Do not rev	NO	R 1 450.24
2023/06/30	FALSE	Do not rev	NO	R 50.39
2023/06/30	FALSE	Do not rev	NO	R 127 414.61
2023/06/30	FALSE	Do not rev	NO	R 56 742.13
2023/06/30	FALSE	Do not rev	NO	R 23 913.36
2023/06/30	FALSE	Do not rev	NO	R 12 191.12
2023/06/30	FALSE	Do not rev	NO	R 47 077.17
2023/06/30	FALSE	Do not rev	NO	R 47 077.17
2023/06/30	FALSE	Do not rev	NO	R 53.30
2023/06/30	FALSE	Review UL	NO	R 1 728.26
2023/06/30	FALSE	Do not rev	NO	R 125.97
2023/06/30	FALSE	Do not rev	NO	R 14 731.63
2023/06/30	FALSE	Do not rev	NO	R 74.62
2023/06/30	FALSE	Do not rev	NO	R 50.39
2023/06/30	FALSE	Do not rev	NO	R 35 696.50
2023/06/30	FALSE	Do not rev	NO	R 62.96
2023/06/30	FALSE	Do not rev	NO	R 54 948.54
2023/06/30	FALSE	Do not rev	NO	R 150 639.94
2023/06/30	FALSE	Do not rev	NO	R 62.96

2023/06/30	FALSE	Review UL	NO	R	1 728.26
2023/06/30	FALSE	Do not rev	NO	R	35 696.50
2023/06/30	FALSE	Do not rev	NO	R	5 211.56
2023/06/30	FALSE	Do not rev	NO	R	11 028.78
2023/06/30	FALSE	Do not rev	NO	R	11 028.78
2023/06/30	FALSE	Do not rev	NO	R	37 000.02
2023/06/30	FALSE	Do not rev	NO	R	157.40
2023/06/30	FALSE	Do not rev	NO	R	870.14
2023/06/30	FALSE	Review UL	NO	R	322 893.43
2023/06/30	FALSE	Review UL	NO	R	42 525.00
2023/06/30	FALSE	Do not rev	NO	R	65 505.93
2023/06/30	FALSE	Do not rev	NO	R	4 302.99
2023/06/30	FALSE	Do not rev	NO	R	870.14
2023/06/30	FALSE	Do not rev	NO	R	1 166 947.41
2023/06/30	FALSE	Do not rev	NO	R	1 522.75
2023/06/30	FALSE	Do not rev	NO	R	22 659.81
2023/06/30	FALSE	Do not rev	NO	R	50 882.68
2023/06/30	FALSE	Do not rev	NO	R	25 403.03
2023/06/30	FALSE	Do not rev	NO	R	48 241.26
2023/06/30	FALSE	Do not rev	NO	R	216 651.77
2023/06/30	FALSE	Do not rev	NO	R	5 966.14
2023/06/30	FALSE	Do not rev	NO	R	11 502.95
2023/06/30	FALSE	Do not rev	NO	R	21 844.51
2023/06/30	FALSE	Do not rev	NO	R	2 175.36
2023/06/30	FALSE	Do not rev	NO	R	35 826.57
2023/06/30	FALSE	Do not rev	NO	R	80 448.66
2023/06/30	FALSE	Do not rev	NO	R	10 569.11
2023/06/30	FALSE	Do not rev	NO	R	2 175.36
2023/06/30	FALSE	Do not rev	NO	R	26 619.47
2023/06/30	FALSE	Do not rev	NO	R	125.97
2023/06/30	FALSE	Do not rev	NO	R	9 812.15
2023/06/30	FALSE	Do not rev	NO	R	28 936.89
2023/06/30	FALSE	Do not rev	NO	R	12 457.40
2023/06/30	FALSE	Do not rev	NO	R	1 171.67
2023/06/30	FALSE	Do not rev	NO	R	2 175.36
2023/06/30	FALSE	Do not rev	NO	R	35 241.10
2023/06/30	FALSE	Do not rev	NO	R	10 826.33
2023/06/30	FALSE	Do not rev	NO	R	92 333.20
2023/06/30	FALSE	Do not rev	NO	R	125.97
2023/06/30	FALSE	Do not rev	NO	R	88.18
2023/06/30	FALSE	Do not rev	NO	R	176.36
2023/06/30	FALSE	Do not rev	NO	R	62.99
2023/06/30	FALSE	Do not rev	NO	R	74.62
2023/06/30	FALSE	Do not rev	NO	R	54 948.54
2023/06/30	FALSE	Do not rev	NO	R	165 380.78
2023/06/30	FALSE	Do not rev	NO	R	251.49
2023/06/30	FALSE	Do not rev	NO	R	252 973.85
2023/06/30	FALSE	Do not rev	NO	R	54 948.54

2023/06/30	FALSE	Do not rev	NO	R	42.16
2023/06/30	FALSE	Do not rev	NO	R	54 948.54
2023/06/30	FALSE	Do not rev	NO	R	37 029.31
2023/06/30	FALSE	Do not rev	NO	R	38 463.98
2023/06/30	FALSE	Do not rev	NO	R	54 948.54
2023/06/30	FALSE	Do not rev	NO	R	5 488.32
2023/06/30	FALSE	Do not rev	NO	R	54 948.54
2023/06/30	FALSE	Do not rev	NO	R	54 948.54
2023/06/30	FALSE	Do not rev	NO	R	744.89
2023/06/30	FALSE	Do not rev	NO	R	4 457.17

28 476 631.05
